





report date: 2024-03-28

General information

Make	ABARTH
Model	500 ABARTH
Colour	Black
Year of manufacture	2009
Top speed	129 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	135 BHP
Max. torque	180 Nm at 2.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	43.5 mpg
CO2 emission	155 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 2

, _	
Date	2022-12-13
Pictures	0
Listing price	View report

source: autotrader.co.uk

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-05-09
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	23
Total items failed	6

MOT #15	2023-05-09 13:38
MOT test number	247699727120
Result	✓ Passed
Next expiry date	2024-05-09
Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	

MOT #14		2022-05-09 15:37
MOT test	number	812036096841
Result		✓ Passed
Minor	Offside Front Inner Drive shaft joint constant velocity boot severely deter	riorated (6.1.7 (g) (i))
Advice	Offside Headlamp damaged	
Advice rear bush	Front Suspension arm pin or bush worn but not resulting in excessive metas. (5.3.4 (a) (i))	ovement both front arms

MOT #13	2021-05-10 11:44
MOT test number	232891480937
Result	✓ Passed

MOT #12	2021-05-10 10:28
MOT test number	er 203341316212
Result	▼ Failed
DANGEROUS (5.2.3 (d) (ii))	Nearside Front Inner Tyre has a tear, caused by separation or partial failure of its structure

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #11 2019-04-27 11:03

MOT test number 415203977749

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10 2018-04-05 10:25

MOT test number 651799360491

Result \rightarrow Passed

Advice Nearside Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

MOT #9 2017-04-20 14:14

MOT test number 436809800215

Result ✓ Passed

Advice Rear Inner Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Advice Nearside Front Tyre worn close to the legal limit on inner edge (4.1.E.1)

MOT #8 2016-04-29 11:35

MOT test number 337912483486

Result

Passed

Advice Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

MOT #7 2016-04-29 11:35

MOT test number 316333584097

Result × Failed

Advice Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Pass with rectification Nearside Rear Brake pipe inadequately supported (3.6.B.1)

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

498756005176

Result

Advice Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Advice Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2015-04-15 16:24 **MOT** test number 315815605123 Result × Failed Fail Offside Front wheel bearing rough when rotated (2.5.A.2) **Advice** Front Tyre worn close to the legal limit (4.1.E.1) **Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c) Fail Offside Additional braking device insecure (3.6.I.1) **Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

MOT #4 2014-05-03 09:47
MOT test number 697913724114

Result ✓ Passed

MOT #3 2013-05-28 13:41
MOT test number 807628343128

Result \(\sqrt{Passed} \)

Advice Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

CarCheck.co.uk page 5/13



WA090XT

report date: 2024-03-28

MOT #2 2013-05-23 11:15

MOT test number 587123943178

Result

× Failed

Fail Nearside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Offside Inner Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Nearside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)

Advice Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

MOT #1 2012-05-21 16:56

MOT test number 696292642127

Result ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	9 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this ABARTH. See if, where and when this ABARTH had damage and the car repair costs. We also check if this ABARTH was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra ABARTH salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this ABARTH in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

e when miscory	
For how long did the current and previous owner(s) have this ABARTH? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this ABARTH had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	UK UK
Flate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this ABARTH is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this ABARTH has been settled.

If not, and you buy this ABARTH then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this ABARTH is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-05-23
Last registration	2023-05-09
Complete history	See info



Registration #1	2009-05-23	25 mi
Registration #2	2012-05-21	37.832 mi
Registration #3	2013-05-23	43.430 mi
Registration #4	2013-05-28	43.430 mi
Registration #5	2014-05-03	48.900 mi
Registration #6	2015-04-15	53.133 mi
Registration #7	2015-04-16	53.133 mi
Registration #8	2016-04-29	63.627 mi
Registration #9	2016-04-29	63.627 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 12/13



WA09OXT report date: 2024-03-28

Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3657 mm
Wheel base	2300 mm
Kerb weight	1035 kg
Max. allowed weight	1425 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	1418802

CarCheck.co.uk page 13/13