



report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 MOMENTUM AWD
Colour	Grey
Year of manufacture	2015
Top speed	137 mph
0 - 60 mph	7.8 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	222 BHP
Max. torque	470 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	52.3 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-06
Pictures	9
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-04-04
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	15
Total items failed	2

MOT #8	2024-04-05 13:06
MOT test number	137610587684
Result	✓ Passed
Next expiry date	2025-04-04

MOT #7	2022-10-04 14:51
MOT test number	129609378528
Result	✓ Passed

MOT #6	2021-08-03 13:36
MOT test number	512928316030
Result	✓ Passed

MOT #5	2020-06-05 15:05
MOT test number	658367458462
Result	✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #4** 2019-07-18 12:10**MOT test number** 900562508746**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2019-07-11 10:10**MOT test number** 317672488123**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #2** 2018-06-27 13:04**MOT test number** 458174716458**Result** ✓ Passed**Advice** Nearside Front tyre cuts in tread**Advice** Nearside Rear damage to tyre side wall**Advice** Offside Front tyre cuts in tread**MOT #1** 2018-06-20 10:33**MOT test number** 230100392046**Result** ✗ Failed**Advice** Offside Front tyre cuts in tread**Advice** Nearside Front tyre cuts in tread**Advice** Nearside Rear damage to tyre side wall**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
4 April 2025

Tax status	Valid until 1 October
Days left	156
MOT expiry date	4 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-07-13
Last registration	2024-04-05
Complete history	See info



Registration #1	2015-07-13	10 mi
Registration #2	2018-06-20	42.434 mi
Registration #3	2018-06-27	42.442 mi
Registration #4	2019-07-11	58.091 mi
Registration #5	2019-07-18	58.093 mi
Registration #6	2019-07-20	58.097 mi
Registration #7	2019-07-20	58.097 mi
Registration #8	2019-07-20	58.097 mi
Registration #9	2019-07-20	58.097 mi
Registration #10	2019-07-20	58.097 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2140 mm
Height	1775 mm
Length	4950 mm
Wheel base	2984 mm
Kerb weight	2064 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1294880