





General information

| Make | HONDA |
|---------------------|--------------|
| Model | LOGO 8V |
| Colour | Silver |
| Year of manufacture | 2000 |
| Top speed | 90 mph |
| 0 - 60 mph | 14.5 seconds |
| Gearbox | 1 speed CVT |

Engine & fuel consumption

| Power | 64 BHP |
|-------------------------|---------------------|
| Max. torque | 108 Nm at 2.500 rpm |
| Engine capacity | 1.343 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 32.5 mpg |
| Consumption extra urban | 46.3 mpg |
| Consumption combined | 40.4 mpg |



X782MEC report date: 2024-03-28

MOT history

| MOT expiry date | 2021-05-20 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 16 |
| Failed MOT tests | 4 |
| Total advice items | 9 |
| Total items failed | 7 |

| МОТ #20 | 2020-05-21 10:56 |
|------------------|------------------|
| MOT test number | 559496554891 |
| Result | ✓ Passed |
| Next expiry date | 2021-05-20 |

| MOT #19 | 2019-05-01 15:32 |
|-----------------|------------------|
| MOT test number | 875156794237 |
| Result | ✓ Passed |

| MOT #18 | 2019-05-01 15:32 |
|-------------------------|---|
| MOT test number | 344965727054 |
| Result | × Failed |
| Pass with rectification | Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 |
| (b) (ii)) | |
| | |

| MOT #17 | 2018-05-10 15:55 |
|-----------------|------------------|
| MOT test number | 902555336136 |
| Result | ✓ Passed |



| X782MEC |
|-------------------------|
| report date: 2024-03-28 |

| MOT #3 | 16 | 2018-05-10 08:45 |
|--------|---|------------------|
| MOT te | st number | 413048180300 |
| Result | | 🗙 Failed |
| Fail | Nearside Rear Brake pipe excessively corroded (3.6.B.2c) | |
| Fail | Offside Rear Brake pipe excessively corroded (3.6.B.2c) | |
| Fail | Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2) | |

| MOT #15 | 2017-05-15 09:53 |
|-----------------|------------------|
| MOT test number | 431538478658 |
| Result | ✓ Passed |

| MOT #14 | 2016-05-17 15:30 |
|-----------------|------------------|
| MOT test number | 636207991809 |
| Result | ✓ Passed |

| MOT #13 | 2015-10-12 09:04 |
|--|------------------|
| MOT test number | 849330510973 |
| Result | 🗸 Passed |
| Advice Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2) | |

| MOT #12 | | 2014-10-17 14:04 |
|----------|---|------------------|
| MOT test | number | 746190194287 |
| Result | | ✓ Passed |
| Advice | Offside Rear Brake pipe slightly corroded (3.6.B.2c) | |
| Advice | Nearside Rear Brake pipe slightly corroded (3.6.B.2c) | |





| MOT #11 | | 2013-10-18 10:36 |
|------------------|---|------------------|
| MOT test | number | 368441693275 |
| Result | | ✓ Passed |
| Advice Advice | Nearside Rear Brake pipe slightly corroded (3.6.B.2c) Offside Rear Brake pipe slightly corroded (3.6.B.2c) | |
| Advice | Offside Rear Brake pipe slightly corroded (3.6.B.2C) | |

| MOT #10 | | 2012-10-17 11:39 |
|----------|---|------------------|
| MOT test | number | 615271892247 |
| Result | | ✓ Passed |
| Advice | Offside Rear Brake pipe slightly corroded (3.6.B.2c) | |
| Advice | Nearside Rear Brake pipe slightly corroded (3.6.B.2c) | |

| МОТ #9 | 2012-10-17 11:39 | |
|---|------------------|--|
| MOT test number | 358511892299 | |
| Result | × Failed | |
| Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) | | |
| Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c) | | |
| Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c) | | |

| MOT #8 | 2011-10-19 12:18 |
|-----------------|------------------|
| MOT test number | 955112691238 |
| Result | ✓ Passed |

| MOT #7 | 2010-10-15 10:32 |
|-----------------|------------------|
| MOT test number | 392928380264 |
| Result | ✓ Passed |





| МОТ #6 | 2009-10-1 | 4 10:58 |
|-------------------------|---|--------------------|
| MOT test number | 350957 | 589452 |
| Result | ✓ | Passed |
| | | |
| MOT #5 | 2008-10-1 | 3 14:56 |
| MOT test number | 112837 | 788241 |
| Result | ✓ | Passed |
| | | |
| MOT #4 | 2007-10-1 | 2 14:08 |
| MOT test number | 312325 | 787493 |
| Result | ✓ | Passed |
| | | |
| MOT #3 | 2006-10-1 | 9 11:50 |
| MOT test number | 574972 | 696247 |
| Result | ✓ | Passed |
| | | |
| MOT #2 | 2006-10-1 | 9 11:50 |
| MOT test number | 973242 | 696204 |
| Result | > | < Failed |
| Pass with rectification | Nearside Front Windscreen wiper does not clear the windscreen effectively | |
| (8.2.2) | Nearside Front Windscreen wiper does not clear the windscreen enectively | / |
| Pass with rectification | Poor registration plate character(c) likely to be microad (6.2.4b) | |
| Pass with rectification | Rear registration plate character(s) likely to be misread (6.3.4b) | |
| | | |
| MOT #1 | 2005-10-1 | 7 11:46 |

| MOT #1 | 2005-10-17 11:40 |
|-----------------|------------------|
| MOT test number | 344890595256 |
| Result | ✓ Passed |





Tax & MOT check

| X Untaxed | Х МОТ |
|---------------------------------|----------------------------|
| Tax expired: 28 January 2021 | Expired: 20 May 2021 |
| Tax status | Expired at 28 January 2021 |
| Days left | 1187 days too late |
| MOT expiry date | 20 May 2021 |
| Full MOT history | See MOT history |





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|----------|--------------|
| Date | | |
| Category | | Lawer |
| Туре | (******* | |
| Damage 2 | | AMPLE |
| Damage 2 | | E CONTRACTOR |
| Date | | |
| Category | | AMP |
| Туре | | |

Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ana | |
|--|-------------|
| ************ | |
| ******* | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this HONDA had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 19 |
| First mileage registration | 2000-10-31 |
| Last registration | 2020-05-21 |
| Complete history | <u>See info</u> |



| Registration #1 | 2000-10-31 | 13 mi |
|------------------|------------|------------|
| Registration #2 | 2005-10-17 | 42.022 mi |
| Registration #3 | 2006-10-19 | 53.263 mi |
| Registration #4 | 2007-10-12 | 64.613 mi |
| Registration #5 | 2008-10-13 | 73.050 mi |
| Registration #6 | 2009-10-14 | 78.878 mi |
| Registration #7 | 2010-10-15 | 83.992 mi |
| Registration #8 | 2011-10-19 | 88.585 mi |
| Registration #9 | 2012-10-17 | 95.962 mi |
| Registration #10 | 2013-10-18 | 103.561 mi |
| Registration #11 | | 11.707 est |
| Registration #12 | | 11.777 est |
| Registration #13 | | 11.707 est |
| Registration #14 | | 11.777 est |
| Registration #15 | | 11.777 esi |
| Registration #16 | | 11.777 est |
| Registration #17 | | 11.777 est |
| Registration #18 | | |
| | | 11.717 au |

More info \rightarrow





Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|------------------------|-----------------------|
| Width | 1645 mm |
| Height | 1524 mm |
| Length | 3785 mm |
| Kerb weight | 880 kg |
| Additional information | |
| Fuel tank capacity | 40 |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of axles | 2 |
| Engine number | D13B71103774 |