





report date: 2024-03-28

#### General information

Make	NISSAN
Model	ALMERA SE
Colour	Silver
Year of manufacture	2004
Top speed	110 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	97 BHP
Max. torque	136 Nm at 4.000 rpm
Engine capacity	1.497 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	160 g/km
CO2 label	G



CarCheck.co.uk page 1/13



MOT history

MOT expiry date	2021-05-28
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	24
Total items failed	6

MOT #18	2020-05-19 12:18
MOT test number	860635372503
Result	✓ Passed
Next expiry date	2021-05-28
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #17		2019-05-29 09:09
MOT test	number	175073123913
Result		✓ Passed
Advice	Brake pipe corroded, covered in grease or other material BOTH FRONT TO	) REARS (1.1.11 (c))

MOT #16	2018-05-25 15:02
MOT test number	128059688553
Result	<b>✓</b> Passed
Advice Offside front to rear brake pip corroded	

CarCheck.co.uk page 2/13



MOT #15 2018-05-25 09:33

MOT test number 908741342196

Result X Failed

Advice Unable to check both front wheel bearings as both brakes are binding

Minor Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3.5mm (5.2.3 (e))

**Fail** Nearside Headlamp insecure (4.1.1 (c))

**Fail** Offside Front Service brake excessively binding (1.2.1 (f))

**Advice** Offside front to rear brake pip corroded

**Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Fail Nearside Front Service brake excessively binding (1.2.1 (f))

**MOT #14** 2017-05-10 17:14

**MOT test number** 979075895056

**Result** ✓ Passed

**Advice** Both front brakes slightly binding

**MOT #13** 2016-04-13 13:53

**MOT test number** 458247768427

**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 3/13



**MOT #12** 2016-04-12 15:04

MOT test number 597091382529

**Result** X Failed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Fail** Offside Front front brake binding (3.7.B.1)

**MOT #11** 2015-04-20 13:42

MOT test number 167740615126

**Result** ✓ Passed

MOT #10 2014-03-21 11:55

**MOT test number** 979150184071

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #9 2013-04-04 17:20

MOT test number 995914593042

Result \( \sqrt{Passed} \)

**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2013-04-03 14:46

MOT test number 138643393468

Result X Failed

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)

**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 4/13



**MOT #7** 2012-03-28 09:01

MOT test number 198178082457

**Result** ✓ Passed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #6 2011-04-07 16:54

**MOT test number** 449637791075

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2011-04-06 11:10

MOT test number 169426491013

Result X Failed

Fail Offside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2010-04-12 10:29

**MOT test number** 251952800129

**Result** 
✓ Passed

MOT #3 2009-04-01 10:40

**MOT test number** 393711199049

**Result** 
✓ Passed

CarCheck.co.uk page 5/13



MOT #2

MOT test number

Result

Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Power steering component(s) has slight seepage from a component (2.3.3b)

 MOT #1
 2007-04-02 15:10

 MOT test number
 850452297075

 Result
 ✓ Passed

CarCheck.co.uk page 6/13





#### Tax & MOT check



Tax expired: 14 December 2020

# **Х** мот

Expired: 28 May 2021

Tax status	Expired at 14 December 2020
Days left	1231 days too late
MOT expiry date	28 May 2021
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



# Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	
**************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	
Current registration	UK NEW
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2004-04-13
Last registration	2020-05-19
Complete history	See info



Registration #1	2004-04-13	6 mi
Registration #2	2007-04-02	18.755 mi
Registration #3	2008-04-08	24.958 mi
Registration #4	2009-04-01	29.879 mi
Registration #5	2010-04-12	34.986 mi
Registration #6	2011-04-06	39.005 mi
Registration #7	2011-04-07	39.005 mi
Registration #8	2012-03-28	42.882 mi
Registration #9	2013-04-03	48.442 mi
Registration #10	2013-04-04	48.442 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		0.77 44
Registration #19		0.00 44

More info >

CarCheck.co.uk page 12/13



# Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
S0567	
50569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1179 kg
Max. allowed weight	1710 kg

# Additional information

Fuel tank capacity	60 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2
Engine number 267070