



BN56KBY


report date: 2024-03-28

General information

Make	JAGUAR
Model	XJ TDVI EXECUTIVE
Colour	Grey
Year of manufacture	2006
Top speed	141 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	205 BHP
Max. torque	435 Nm at 1.900 rpm
Engine capacity	2.720 cc
Cylinders	6
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.9 mpg
CO2 emission	214 g/km
CO2 label	K





Internet history

Entry 6

Date	2023-01-12
Pictures	16
Listing price	View report



source: [autotrader.co.uk](#)

Entry 5

Date	2022-12-01
Pictures	17
Listing price	View report



source: [autotrader.co.uk](#)

Entry 4

Date	2022-03-17
Pictures	19
Listing price	View report



source: [cargurus.co.uk](#)

Entry 3

Date	2022-02-03
------	------------

Pictures

19

Listing price

[View report](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 2

Date

2021-10-01

Pictures

18

Listing price

[View report](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date


2021-09-28

Pictures

18

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-07
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	16
Total items failed	8

MOT #14	2023-11-08 17:26
MOT test number	523918011682
Result	✓ Passed
Next expiry date	2024-11-07
Minor	Nearside Front Brake hose slightly chafed (1.1.12 (b) (i))

MOT #13	2023-11-08 16:53
MOT test number	709157393989
Result	✗ Failed
Fail	Offside Rear Tyre has a tear, caused by separation or partial failure of its structure also worn and flat 255/40r19 (5.2.3 (d) (ii))
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Minor	Nearside Front Brake hose slightly chafed (1.1.12 (b) (i))
Fail	Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure also worn (5.2.3 (d) (ii))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Minor	Nearside Front Position lamp incorrect colour (4.2.3 (a) (i))

MOT #12	2022-09-02 09:01
MOT test number	842638211496
Result	✓ Passed
Advice	Manufactures covers and under tray fitted unable to fully inspect vehicle

**MOT #11** 2022-06-06 15:14**MOT test number** 939278842325**Result** ✓ Passed**Advice** Manufactures covers and under tray fitted unable to fully inspect vehicle**MOT #10** 2022-04-12 15:39**MOT test number** 956322766107**Result** ✓ Passed**MOT #9** 2021-05-21 15:27**MOT test number** 855167386414**Result** ✓ Passed**MOT #8** 2016-12-14 12:42**MOT test number** 332077983897**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Rear Brake pipe slightly corroded main (3.6.B.2c)**Advice** Vehicle has outer sills + floor covers fitted**Advice** Nearside Front Lower Shock absorber has a slightly worn bush (2.7.4)**Advice** Both front tyres stepping on inner edges + n/s/r tyre wearing on inner edge**MOT #7** 2015-12-14 09:24**MOT test number** 640420812184**Result** ✓ Passed**Advice** Under tray/engine covers fitted**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #6** 2015-01-06 10:19**MOT test number** 306786805081**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2014-01-14 10:32**MOT test number** 758604114044**Result** ✓ Passed**MOT #4** 2012-10-17 15:22**MOT test number** 497841592238**Result** ✓ Passed**MOT #3** 2010-11-02 17:00**MOT test number** 641476400341**Result** ✓ Passed**MOT #2** 2009-10-30 16:30**MOT test number** 261403409373**Result** ✓ Passed



MOT #1	2009-10-28 16:14
MOT test number	920461609340
Result	✗ Failed
Fail	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
7 November 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	7 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	BN56KBY
Plate since	2024-03-28
Current registration	BN56KBY
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-09-29
Last registration	2023-11-08
Complete history	See info



Registration #1	2006-09-29	17 mi
Registration #2	2009-10-28	23.290 mi
Registration #3	2009-10-30	23.318 mi
Registration #4	2010-11-02	47.860 mi
Registration #5	2012-10-17	40.981 mi
Registration #6	2014-01-14	47.292 mi
Registration #7	2015-01-06	55.724 mi
Registration #8	2015-12-14	63.020 mi
Registration #9	2016-12-14	74.189 mi
Registration #10	2021-05-21	79.540 mi
Registration #11	2022-05-22	81.277 mi
Registration #12	2022-05-22	81.277 mi
Registration #13	2022-05-22	81.277 mi
Registration #14	2022-05-22	81.277 mi
Registration #15	2022-05-22	81.277 mi
Registration #16	2022-05-22	81.277 mi
Registration #17	2022-05-22	81.277 mi
Registration #18	2022-05-22	81.277 mi
Registration #19	2022-05-22	81.277 mi
Registration #20	2022-05-22	81.277 mi
Registration #21	2022-05-22	81.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2108 mm
Height	1448 mm
Length	5090 mm
Wheel base	3034 mm
Kerb weight	1659 kg
Max. allowed weight	2283 kg

Additional information

Fuel tank capacity	85 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	00766447G