



Mercedes-Benz

 **KR06TKT**

report date: 2024-03-28

General information

Make	MERCEDES
Model	VITO 109 CDI LONG P/V
Colour	Silver
Year of manufacture	2006
Gearbox	6 speed Manual

Engine & fuel consumption

Power	88 BHP
Max. torque	240 Nm at 1.400 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-31
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-19
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	28
Total items failed	8

MOT #18	2023-09-20 11:47
MOT test number	180323690088
Result	✓ Passed
Next expiry date	2024-09-19
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))
Advice	Power steering component has slight seepage from a component (2.1.5 (a))
Advice	Rear Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Offside Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #17	2023-09-19 10:51
MOT test number	243249836782
Result	✗ Failed
Advice	Rear Oil leak, but not excessive (8.4.1 (a) (i))
MAJOR	Registration plate lamp inoperative in the case of a single lamp or all lamps both sides (4.7.1 (b) (ii))
Minor	Offside Obligatory mirror slightly damaged (3.3 (b) (i))
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))
Advice	Power steering component has slight seepage from a component (2.1.5 (a))

**MOT #16**

2022-12-01 11:44

MOT test number

172253139548

Result

✓ Passed

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security Inner Sill Area Next To Rear Axle Mounting (6.2.2 (d) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #15**

2021-12-14 11:34

MOT test number

933367019832

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14**

2020-11-21 13:23

MOT test number

546548560018

Result

✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**MOT #13**

2019-11-26 08:31

MOT test number

200847142758

Result

✓ Passed

Advice Rear drive shaft gaiter perished (both rear)**MOT #12**

2018-10-30 08:29

MOT test number

253048755348

Result

✓ Passed

**MOT #11** 2017-10-31 10:35**MOT test number** 757911372352**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Oil leak diff**MOT #10** 2016-10-31 14:36**MOT test number** 144891602296**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #9** 2016-10-31 10:26**MOT test number** 750239105866**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Front Tyre fouling a part of the vehicle (4.1.D.2)**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**Fail** Nearside Rear Coil spring not correctly located (2.4.C.2)**MOT #8** 2015-11-02 10:44**MOT test number** 247640091339**Result** ✓ Passed

**MOT #7** 2014-10-20 12:23**MOT test number** 848923194213**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #6** 2013-10-28 10:01**MOT test number** 207391403360**Result** ✓ Passed**MOT #5** 2012-10-19 10:47**MOT test number** 968833592218**Result** ✓ Passed**Advice** Nearside Rear coil spring worn (2.4.C.1b)**MOT #4** 2011-10-18 10:56**MOT test number** 308741891490**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #3** 2010-10-21 11:35**MOT test number** 311824790421**Result** ✓ Passed



MOT #22010-03-10 16:12

MOT test number170599460018

Result		✗ Failed
Fail	Parking brake lever has no reserve travel (3.1.6b)	
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail	Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)	
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #12009-04-08 10:01

MOT test number754198999025

Result		✓ Passed
--------	--	----------



Tax & MOT check

X

Untaxed

Tax expired:
1 March 2024

✓

MOT

Expires:
19 September 2024

Tax status	Expired at 1 March 2024
Days left	58 days too late
MOT expiry date	19 September 2024
Full MOT history	See MOT history



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-06-01
Last registration	2023-09-20
Complete history	See info



Registration #1	2006-06-01	11 mi
Registration #2	2009-04-08	43.395 mi
Registration #3	2010-03-10	54.128 mi
Registration #4	2010-10-21	67.556 mi
Registration #5	2011-10-18	70.925 mi
Registration #6	2012-10-19	74.994 mi
Registration #7	2013-10-28	81.429 mi
Registration #8	2014-10-20	87.560 mi
Registration #9	2015-11-02	94.152 mi
Registration #10	2016-10-31	101.541 mi
Registration #11	2016-10-31	101.541 mi
Registration #12	2016-10-31	101.541 mi
Registration #13	2016-10-31	101.541 mi
Registration #14	2016-10-31	101.541 mi
Registration #15	2016-10-31	101.541 mi
Registration #16	2016-10-31	101.541 mi
Registration #17	2016-10-31	101.541 mi
Registration #18	2016-10-31	101.541 mi
Registration #19	2016-10-31	101.541 mi
Registration #20	2016-10-31	101.541 mi

More info >



Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	64698350216006