





## General information

Make	MAZDA
Model	5 TS2
Colour	Grey
Year of manufacture	-
Top speed	113 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	114 BHP
Max. torque	165 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.8 mpg





## Internet history


Entry 1

Date Pictures 2021-12-03

23

Listing price

View report



source: autotrader.co.uk



# MOT history

MOT #16	2022-11-07 17:02
MOT test number	344498730015
Result	✓ Passed
Next expiry date	2023-11-06

MOT #15	2022-11-07 10:41
MOT test number	656708531889
Result	🗙 Failed
<b>DANGEROUS</b> Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a	a) (ii))
<b>MAJOR</b> Offside Headlamp not working on dipped beam (4.1.1 (a) (i	i))

MOT #14	2021-10-21 14:40
MOT test number	628616423477
Result	✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13		2021-10-11 11:30
MOT test	number	414958631900
Result		🗙 Failed
MAJOR	Offside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
DANGER	<b>OUS</b> Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (	e))
MAJOR	Nearside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		

Result







MOT #11	2019-07-25 09:06
MOT test number	735967315253
Result	✓ Passed
MOT #10	2018-07-25 09:15
MOT test number	469495846265
Result	✓ Passed
МОТ #9	2017-07-26 14:56
MOT test number	680878659153
Result	✓ Passed
MOT #8	2017-07-25 11:15
MOT test number	903257993151
Result	× Failed
Fail         Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail         Offside Front Tyre has ply or cords exposed (4.1.D.1b)	
<b>Fail</b> Offside Rear Suspension arm rubber bush deteriorated resulting in excessive movement front bush (2.4.G.2)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #7	2016-07-27 09:49
MOT test number	908463790000
Result	✓ Passed
MOT #6	2015-07-20 15:04

MOT #6	2013-07-20 13.04
MOT test number	796001505278
Result	✓ Passed





MOT #5	2014-07-21 12:44
MOT test number	267332504246
Result	✓ Passed
MOT #4	2013-07-23 11:03
MOT test number	446374203229
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #3	2012-07-24 10:08

	2012 07 21 10.00
MOT test number	277626102283
Result	✓ Passed
Notice Nail in offside rear tyre	

MOT #2	2011-08-03 11:59
MOT test number	185615311234
Result	✓ Passed

MOT #1	2010-07-15 10:29
MOT test number	142406190106
Result	✓ Passed





### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. ALANPE
Туре	
Damage 2	AMPL
Damage 2	E CUT-S
Date	14 N
Category	AMP
Туре	

#### Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
********	
*******	
**********	
********	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-08-01
Last registration	2022-11-07
Complete history	See info



Registration #1	2007-08-01	13 mi
Registration #2	2010-07-15	9.894 mi
Registration #3	2011-08-03	18.874 mi
Registration #4	2012-07-24	27.118 mi
Registration #5	2013-07-23	38.716 mi
Registration #6	2014-07-21	50.332 mi
Registration #7	2015-07-20	61.543 mi
Registration #8	2016-07-27	70.257 mi
Registration #9	2017-07-25	77.981 mi
Registration #10		11.777 esi
Registration #11		11.777 est
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		0.777 est
Registration #17		11.777 mi
Registration #18		11.117 esi

More info >





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1755 mm
Height	1655 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1512 kg
Max. allowed weight	2090 kg
Additional information	
Additional information Fuel tank capacity	60 l
	60 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5