



AE53HKZ

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT SPORT 20V TURBO (150BHP)
Colour	Blue
Year of manufacture	-
Top speed	137 mph
0 - 60 mph	9.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	210 Nm at 1.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	24.6 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.0 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-17
Pictures	22
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #19** 2021-11-16 14:20**MOT test number** 913157355977**Result** ✓ Passed**Next expiry date** 2022-12-01**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement Both front (5.3.4 (a) (i))**Minor** Front Drive shaft joint constant velocity boot severely deteriorated Both front (6.1.7 (g) (i))**MOT #18** 2021-11-16 14:20**MOT test number** 618763960176**Result** ✗ Failed**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement Both front (5.3.4 (a) (i))**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Front Drive shaft joint constant velocity boot severely deteriorated Both front (6.1.7 (g) (i))**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #17**

2020-11-25 12:10

MOT test number

690621563448

Result

✓ Passed

- Advice** Front Exhaust has a minor leak of exhaust gases flexy (6.1.2 (a))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Tyre worn close to legal limit/worn on edge both sides edges (5.2.3 (e))
- Minor** Front Outer Drive shaft joint constant velocity boot severely deteriorated both sides (6.1.7 (g) (i))
- Advice** Front Brake hose slightly deteriorated both sides(poor condition) (1.1.12 (b) (ii))
- Minor** Front Headlamp lens slightly defective both sides (poor condition) (4.1.1 (b) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread damage (0.1 (b))

MOT #16

2019-12-02 14:21

MOT test number

825794685455

Result

✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Front Drive shaft joint constant velocity boot severely deteriorated both sides (6.1.7 (g) (i))
- Advice** Front Exhaust has a minor leak of exhaust gases flexy (6.1.2 (a))
- Advice** Headlamp has a product on the lens but not seriously reducing light output both sides (poor conditon) (4.1.4 (b))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened front and rear (poor condition) (1.1.14 (a) (ii))
- Advice** Front Brake hose slightly deteriorated both sides (1.1.12 (b) (ii))
- Advice** Wear edges both front tyres 205/60/15

**MOT #15**

2018-11-26 15:52

MOT test number

235633677598

Result

✓ Passed

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Exhaust has a minor leak of exhaust gases flexy (6.1.2 (a))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened poor condition (1.1.14 (a) (ii))
- Minor** Headlamp lens slightly defective both sides (4.1.1 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened poor condition (1.1.14 (a) (ii))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Front Brake hose slightly deteriorated both sides (1.1.12 (b) (ii))

MOT #14

2017-11-14 12:18

MOT test number

408904343168

Result

✓ Passed

- Advice** Nearside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Brake disc worn, pitted or scored, but not seriously weakened front and rear (3.5.1i)
- Advice** Front registration plate deteriorated but not likely to be misread damage (6.3.1d)
- Advice** Headlamp deteriorated but light output not reduced both sides (1.7.5a)
- Advice** Front Brake hose slightly deteriorated both sides (3.6.B.4d)
- Advice** Front Exhaust has a minor leak of exhaust gases flexy (7.1.2)

**MOT #13**

2016-11-07 09:34

MOT test number

204795881583

Result

✓ Passed

- Advice** Front Brake hose slightly deteriorated both sides (3.6.B.4d)
- Advice** Brake disc worn, pitted or scored, but not seriously weakened front and rear (3.5.1i)
- Advice** Nearside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #12

2016-11-07 09:34

MOT test number

815636730854

Result

✗ Failed

- Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Nearside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Front Brake hose slightly deteriorated both sides (3.6.B.4d)
- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Advice** Brake disc worn, pitted or scored, but not seriously weakened front and rear (3.5.1i)

MOT #11

2015-11-26 09:35

MOT test number

553925358681

Result

✓ Passed

- Advice** Headlamp has a product on the lens but not seriously reducing light output both sides (1.7.5a)
- Advice** Child seat fitted
- Advice** Front Brake hose slightly deteriorated both sides (3.6.B.4d)
- Advice** Nearside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #10** 2014-10-21 09:30**MOT test number** 496934994263**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)**Notice** N/s/r tyre starting to perish 205/60/15**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**Notice** Unable too see inner front brake pads**MOT #9** 2013-10-11 10:01**MOT test number** 539324483216**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2012-03-15 11:28**MOT test number** 825145472002**Result** ✓ Passed**Notice** Cuts in nearside rear tyre outer wall**Notice** Front number plate cracked**Notice** Nearside rear light damaged**Notice** Stone damage to windscreen

**MOT #7**

2012-03-15 11:28

MOT test number

389335172038

Result**✗ Failed****Notice** Front number plate cracked**Notice** Nearside rear light damaged**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Notice** Stone damage to windscreen**Notice** Cuts in nearside rear tyre outer wall**MOT #6**

2011-03-25 09:26

MOT test number

757884481053

Result**✓ Passed****Notice** Front number plate cracked**Notice** Rear discs slightly lipped on edges**Notice** Stone damage to windscreen**Notice** Cuts in offside front and offside rear tyre outer walls**Notice** Offside front tyre wearing close to limit on inner edge

**MOT #5** 2011-03-24 13:01**MOT test number** 349943081050**Result** ✗ Failed

- Notice** Stone damage to windscreen
- Notice** Cuts in offside front and offside rear tyre outer walls
- Notice** Front tyres wearing close to limit on inner edges
- Notice** Front number plate cracked
- Notice** Rear discs slightly lipped on edges

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #4 2010-04-07 11:04**MOT test number** 861617590038**Result** ✓ Passed

- Notice** Front tyres starting to wear low on inner edges
- Notice** Rear brake discs slightly pitted on edges

MOT #3 2009-04-08 11:42**MOT test number** 543508599075**Result** ✓ Passed

- Notice** Stone damage to windscreen

MOT #2 2008-03-31 09:40**MOT test number** 814181498024**Result** ✓ Passed

- Notice** Stone damage to windscreen



MOT #1	2007-03-23 12:36
MOT test number	430142287032
Result	✓ Passed
Notice	Stone damage to windscreen
Notice	Front discs in poor condition



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	AE53HKZ
Plate since	2024-03-29
Current registration	AE53HKZ
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2003-09-23
Last registration	2021-11-16
Complete history	See info



Registration #1	2003-09-23	17 mi
Registration #2	2007-03-23	37.954 mi
Registration #3	2008-03-31	41.497 mi
Registration #4	2009-04-08	44.516 mi
Registration #5	2010-04-07	49.256 mi
Registration #6	2011-03-24	53.625 mi
Registration #7	2011-03-25	53.625 mi
Registration #8	2012-03-15	58.094 mi
Registration #9	2013-10-11	68.753 mi
Registration #10	2014-10-21	74.683 mi
Registration #11	2015-05-20	79.377 mi
Registration #12	2016-05-20	84.071 mi
Registration #13	2017-05-20	88.765 mi
Registration #14	2018-05-20	93.459 mi
Registration #15	2019-05-20	98.153 mi
Registration #16	2020-05-20	102.847 mi
Registration #17	2021-05-20	107.541 mi
Registration #18	2022-05-20	112.235 mi
Registration #19	2023-05-20	116.929 mi
Registration #20	2024-05-20	121.623 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1752 mm
Height	1473 mm
Length	4699 mm
Wheel base	2703 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2

Engine number

AWT 133232