



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Grey
Year of manufacture	2008
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history

Entry 1

Date	2022-02-22
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-23
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	43
Total items failed	12

MOT #20	2023-12-28 16:25
MOT test number	444718411741
Result	✓ Passed
Next expiry date	2025-01-23
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #19	2023-12-28 16:25
MOT test number	591756095575
Result	✗ Failed
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #18	2023-01-24 14:08
MOT test number	387836183645
Result	✓ Passed

**MOT #17** 2021-12-07 13:54**MOT test number** 145683677557**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2020-08-25 12:10**MOT test number** 969829813544**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2019-08-21 15:47**MOT test number** 756223116456**Result** ✓ Passed**Advice** All tyres perished**MOT #14** 2018-08-24 12:46**MOT test number** 124539143611**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13** 2018-08-24 08:38**MOT test number** 958620239301**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #12** 2017-08-25 12:00**MOT test number** 912272837205**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2017-08-25 10:08**MOT test number** 280055698504**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #10**

2016-08-24 14:06

MOT test number

945498728822

Result

✓ Passed

- Advice** Offside Front Direction indicators slightly discoloured (1.4.A.2f)
- Advice** Offside Front Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Advice** Slight oil leak
- Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)
- Advice** Nearside Front Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #9

2015-08-26 00:00

MOT test number

613365223614

Result

✓ Passed

MOT #8

2015-08-26 00:00

MOT test number

978206561314

Result

✗ Failed

- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #7

2015-01-08 17:00

MOT test number

746658505044

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2015-01-07 16:07**MOT test number** 117977705044**Result** ✗ Failed

- Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2014-01-06 15:44**MOT test number** 135656204413**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)

**MOT #4** 2014-01-06 15:44**MOT test number** 216846604058**Result** ✗ Failed**Advice** Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Pass with rectification** Offside Obligatory mirror insecure (8.1.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #3** 2012-08-17 15:38**MOT test number** 948230832265**Result** ✓ Passed**MOT #2** 2012-08-17 14:47**MOT test number** 759730432262**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #1** 2011-07-25 14:24**MOT test number** 898006501223**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
23 January 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	23 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	WR08AYA
Plate since	2024-03-29
Current registration	WR08AYA
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-04-08
Last registration	2023-12-28
Complete history	See info



Registration #1	2008-04-08	10 mi
Registration #2	2011-07-25	30.644 mi
Registration #3	2012-08-17	36.926 mi
Registration #4	2012-08-17	36.926 mi
Registration #5	2014-01-06	55.371 mi
Registration #6	2015-01-07	65.705 mi
Registration #7	2015-01-08	65.705 mi
Registration #8	2015-08-26	72.481 mi
Registration #9	2015-08-26	72.481 mi
Registration #10	2016-08-24	78.551 mi
Registration #11	2017-08-25	84.402 mi
Registration #12	2018-08-26	90.253 mi
Registration #13	2019-08-27	96.104 mi
Registration #14	2020-08-28	101.955 mi
Registration #15	2021-08-29	107.806 mi
Registration #16	2022-08-30	113.657 mi
Registration #17	2023-08-31	119.508 mi
Registration #18	2023-08-31	119.508 mi
Registration #19	2023-08-31	119.508 mi
Registration #20	2023-08-31	119.508 mi
Registration #21	2023-12-28	119.508 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 378141