






General informationMakeLAND ROVERModelFREELANDER TD4 COMMERCIALColourGreenYear of manufacture2006Gearbox5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.951 cc
Cylinders	4
Fuel type	Diesel







Internet history

Entry 1

Date Pictures 2021-06-07

16

Listing price

View report







MOT history

MOT expiry date	2024-06-16
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	48
Total items failed	10

MOT #23	202	23-06-17 08:19
MOT test	number	100617232820
Result		🗸 Passed
Next exp	iry date	2024-06-16
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)))

MOT #22	2022-09-29 14:2
MOT test	number 91980242391
Result	✓ Passe
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Nearside Brake pipe corroded, covered in grease or other material front to rear at rear (1.1.11 (c))
Minor (4.7.1 (b)	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (i))



MOT #21 2022-09-2	8 08:22
MOT test number 885576	5999482
Result	🗙 Failed
Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
MAJOR Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
DANGEROUS Nearside Front Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
MAJOR Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Advice Tyre slightly damaged/cracking or perishing ALL TYRES CRACKING JUST ACCEPTABLE (5.2.3 (ii))	(d)
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light source (4.7.1 (b) (i))	S
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice Nearside Brake pipe corroded, covered in grease or other material front to rear at rear (1.1.	11 (c))
DANGEROUS Offside Rear Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))	
MAJOR Central Prop shaft bearing excessively worn (6.1.7 (b) (i))	

MOT #20		2021-06-17 15:43
MOT test	number	492824996540
Result		✓ Passed
Advice	Front Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))	
Advice	Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))	

MOT #19		2021-06-14 10:57
MOT test	number	667642466245
Result		🗙 Failed
Advice	Front Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))	
Advice	Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))	
MAJOR	Fuel tank insecure support brackets badly corroded (6.1.3 (a) (i))	



MOT #18	2020-11-13 15:08
MOT test number	661180005030
Result	✓ Passed
Advice Fuel Pipe/s corroded fuel tank straps correded	
Advice Exhaust emits excessive smoke or vapour but not likely to obscure the v blue smoke when cold ok when when warm temp at 80 c (8.2.2.2 (c))	ision of other road users

MOT #17		2020-11-13 12:59
MOT test	number	101211994538
Result		🗙 Failed
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
MAJOR	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice	Fuel Pipe/s corroded fuel tank straps correded	
Advice blue smok	Exhaust emits excessive smoke or vapour but not likely to obscure the vision when cold ok when when warm temp at 80 c (8.2.2.2 (c))	on of other road users

MOT #16		2019-10-30 16:25
MOT test	number	927802441546
Result		✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c	:))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11	(c))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11	(c))

MOT #15	2018-11-10 11:33
MOT test number	928900624734
Result	✓ Passed
MOT #14	2017-12-01 16:52
MOT test number	721789685223

✓ Passed

WR06XSB

report date: 2024-03-28

Result





MOT #13	2017-11-29 15:11
MOT test number	231659241250
Result	🗙 Failed
 Fail Offside Rear Lower Trailing arm rubber bush deteriorated resulting in exce Fail Nearside Rear Lower Trailing arm rubber bush bonding deteriorated result (2.4.G.2) 	

MOT #12		2016-12-14 15:16
MOT test	number	692666970924
Result		🗸 Passed
Advice (2.4.G.2)	Offside Rear Tie bar/rod rubber bush deteriorated but not resulting in excessiv	ve movement
Advice (2.4.G.2)	Nearside Rear Tie bar/rod rubber bush deteriorated but not resulting in excess	sive movement

MOT #11	2016-12-14 15:05	
MOT test number	760586322238	
Result	🗙 Failed	
Fail Rear Registration plate lamp not working (1.1.C.1d)		
AdviceNearside Rear Tie bar/rod rubber bush deteriorated but not resulting in excessive movement(2.4.G.2)		
Fail Nearside Windscreen wiper does not clear the windscreen effectively SPLIT (8.2.2)		
Advice Offside Rear Tie bar/rod rubber bush deteriorated but not resulting in excessive (2.4.G.2)	e movement	

MOT #10		2015-12-10 16:11
MOT test	number	479712305031
Result		🗸 Passed
Advice Nearside Rear Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)		sive movement
Advice (2.4.G.2)	Offside Rear Tie bar/rod rubber bush deteriorated but not resulting in excessi	ve movement





MOT #9	2015-12-09 10:44	
MOT test number	463702078210	
Result	🗙 Failed	
Advice Offside Rear Tie bar/rod rubber bush deteriorated but not resulting in excessive (2.4.G.2)	movement	
Fail Registration plate lamp not working (1.1.C.1d)		
Advice Nearside Rear Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)		
Fail Rear Exhaust system not adequately supported (7.1.1)		
Fail Nearside Headlamp not working on dipped beam (1.7.5a)		
Fail Horn not working (1.6.2a)		

MOT #8		2014-06-17 13:59
MOT test	number	597678364126
Result		✓ Passed
Advice (2.4.G.2)	Nearside Rear Trailing arm rubber bush deteriorated but not resulting in exc	essive movement
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice (2.4.G.2)	Offside Rear Trailing arm rubber bush deteriorated but not resulting in exces	ssive movement

MOT #7	2013-06-26 12:05
MOT test number	468817973175
Result	✓ Passed
Notice Oil leak	

MOT #6		2013-06-26 12:05
MOT test number		138977973170
Result		× Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)	
Notice Oil leak		



MOT #5		2012-06-27 14:27
MOT test number		205739572101
Result		✓ Passed
MOT #4		2012-06-27 14:27
MOT test number		829579872160
Result		🗙 Failed
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)	

MOT #3		2011-06-08 16:06
MOT test	number	219649451498
Result		✓ Passed
Advice	Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)	
Advice	Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)	

MOT #2	2010-06-10 10:42
MOT test number	910671260196
Result	✓ Passed
Notice Chip in windscreen	
Notice Nail in n/s rear tyre not repairible	
Notice Both rear tyres are geting low	

MOT #1	2009-06-17 14:45
MOT test number	324518369160
Result	✓ Passed



Tax & MOT check

X Untaxed	✓ MOT
Tax expired: 31 March 2023	Expires: 16 June 2024
Tax status	Expired at 31 March 2023
Days left	396 days too late
MOT expiry date	16 June 2024
Full MOT history	See MOT history





Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	AAMP
Туре	
Damage 2	AMPLE
Date	
	MPLE .
Category	ter .
Туре	

Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

NUMBER OF CONTRACTOR OF CONTRA		

	More info	>
Plate changes		
See in this check if this LAND ROVER had different number plates.		





Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-06-30
Last registration	2023-06-17
Complete history	See info



Registration #3 2010-06-10 65 Registration #4 2011-06-08 78 Registration #5 2012-06-27 92 Registration #6 2013-06-26 96 Registration #7 2014-06-17 92 Registration #8 2015-12-09 100 Registration #9 2016-12-14 100 Registration #10 2016-12-14 100	
Registration #3 2010-06-10 63 Registration #4 2011-06-08 74 Registration #5 2012-06-27 93 Registration #6 2013-06-26 94 Registration #7 2014-06-17 93 Registration #7 2014-06-17 93 Registration #8 2015-12-09 100 Registration #10 2016-12-14 100 Registration #11 2016-12-14 100 Registration #12 2017-11-29 100 Registration #12 2017-11-29 100 Registration #14 100 100 Registration #15 100 100 Registration #16 100 100 Registration #18 100 100 Registration #19 100 100	19 mi
Registration #4 2011-06-08 74 Registration #5 2012-06-27 94 Registration #6 2013-06-26 94 Registration #7 2014-06-17 94 Registration #7 2014-06-17 94 Registration #7 2014-06-17 94 Registration #8 2015-12-09 100 Registration #9 2015-12-10 100 Registration #10 2016-12-14 100 Registration #11 2016-12-14 100 Registration #12 2017-11-29 100 Registration #13 100 100 Registration #14 100 100 Registration #15 100 100 Registration #16 100 100 Registration #17 100 100 Registration #18 100 100 Registration #18 100 100 Registration #19 100 100	.561 mi
Registration #5 2012-06-27 92 Registration #6 2013-06-26 92 Registration #7 2014-06-17 92 Registration #8 2015-12-09 100 Registration #9 2015-12-10 100 Registration #10 2016-12-14 100 Registration #11 2016-12-14 100 Registration #12 2017-11-29 100 Registration #13 2015-12-10 100 Registration #14 2016-12-14 100 Registration #13 2017-11-29 100 Registration #14 2017-11-29 100 Registration #15 2017-11-29 100 Registration #14 2016-12-14 100 Registration #14 2016-12-14 100 Registration #14 2017-11-29 100 Registration #14 2016-12-14 100 Registration #15 2017-11-29 100 Registration #16 2016-12-14 100 Registration #17 2016-12-14 100 Registration #18 2016-12-14 100 Registr	.213 mi
Registration #6 2013-06-26 94 Registration #7 2014-06-17 95 Registration #8 2015-12-09 100 Registration #9 2015-12-10 100 Registration #10 2016-12-14 100 Registration #11 2016-12-14 100 Registration #12 2017-11-29 100 Registration #13 100 100 Registration #14 100 100 Registration #15 100 100 Registration #16 100 100 Registration #17 100 100 Registration #18 100 100 Registration #18 100 100 Registration #14 100 100 Registration #16 100 100 Registration #16 100 100 Registration #18 100 100 Registration #19 100 100	.762 mi
Registration #7 2014-06-17 97 Registration #8 2015-12-09 100 Registration #9 2015-12-10 100 Registration #10 2016-12-14 100 Registration #11 2016-12-14 100 Registration #12 2017-11-29 100 Registration #13 2017-11-29 100 Registration #14 2017-11-29 100 Registration #15 2017-11-29 100 Registration #16 2017-11-29 100 Registration #16 2017-11-29 100 Registration #16 2017-11-29 100 Registration #17 2017-11-29 100 Registration #16 2017-11-29 100 Registration #17 2017-11-29 100 Registration #16 2017-11-29 100 Registration #17 2017-11-29 100 Registration #18 2017-11-29 100 Registration #19 2017-11-29 100	.672 mi
Registration #8 2015-12-09 100 Registration #9 2015-12-10 100 Registration #10 2016-12-14 100 Registration #11 2016-12-14 100 Registration #12 2017-11-29 100 Registration #13 2017-11-29 100 Registration #14 2017-11-29 100 Registration #15 2017-11-29 100 Registration #16 2017-11-29 100 Registration #18 2017-11-29 100 Registration #18 2017-11-29 100 Registration #19 2017-11-29 100	.243 mi
Registration #9 2015-12-10 100 Registration #10 2016-12-14 100 Registration #11 2016-12-14 100 Registration #12 2017-11-29 100 Registration #13 2017-11-29 100 Registration #14 2016-12-14 100 Registration #14 2017-11-29 100 Registration #15 2017-11-29 100 Registration #16 2017-11-29 100 Registration #17 2017-11-29 100 Registration #18 2017-11-29 100 Registration #19 2017-11-29 100	.258 mi
Registration #10 2016-12-14 101 Registration #11 2016-12-14 101 Registration #12 2017-11-29 101 Registration #13 2017-11-29 101 Registration #14 2016-12-14 101 Registration #14 2017-11-29 101 Registration #14 2017-11-29 101 Registration #14 2016-12-14 101 Registration #14 2017-11-29 101 Registration #14 2016-12-14 101 Registration #15 2017-11-29 101 Registration #15 2017-11-29 101 Registration #15 2017-11-29 101 Registration #16 2017-11-29 101 Registration #17 2017-11-29 101 Registration #18 2017-11-29 101 Registration #19 2017-11-29 101	.721 mi
Registration #112016-12-14101Registration #122017-11-29101Registration #13Image: Stration #14Image: Stration #14Registration #14Image: Stration #15Image: Stration #16Registration #16Image: Stration #17Image: Stration #18Registration #18Image: Stration #19Image: Stration #19	.745 mi
Registration #122017-11-29102Registration #13Registration #14102Registration #14102102Registration #15102102Registration #16102102Registration #17102102Registration #18102102Registration #19102102	485 mi
Registration #13Registration #14Registration #15Registration #16Registration #17Registration #18Registration #19	.485 mi
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19	.657 mi
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19	1,777 mi
Registration #16 Registration #17 Registration #18 Registration #19	1,777 mi
Registration #17 Registration #18 Registration #19	1,777 mi
Registration #18 Registration #19	1,777 mi
Registration #19	1,777 mi
Registration #20	1,777 mi
Registration #21	
Registration #22	1,777 mi
Registration #23	

More info >



Safety ratings

NCAP rating

Video

see crash video

Dimensions & weight	
Width	2071 mm
Kerb weight	1515 kg
Max. allowed weight	2050 kg
Additional information	
Number of seats	3
Number of axles	2
Engine number	80146074