





report date: 2024-03-29

General information

| Make | FIAT |
|---------------------|----------------|
| Model | 500 LOUNGE |
| Colour | Grey |
| Year of manufacture | 2017 |
| Top speed | 99 mph |
| 0 - 60 mph | 12.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 69 BHP | |
|-------------------------|---------------------|--|
| Max. torque | 102 Nm at 3.000 rpm | |
| Engine capacity | 1.242 cc | |
| Cylinders | 4 | |
| Fuel type | Petrol | |
| Consumption city | 51.4 mpg | |
| Consumption extra urban | 65.7 mpg | |
| Consumption combined | 60.1 mpg | |
| CO2 emission | 110 g/km | |
| CO2 label | В | |



CarCheck.co.uk page 1/11



Internet history

Entry 1

| Date | 2021-06-18 |
|---------------|-------------|
| Pictures | 1 |
| Listing price | View report |



source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2024-10-18 |
|--------------------|------------|
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 8 |
| Total items failed | 6 |

| MOT #6 | 2023-10-19 16:01 |
|------------------|------------------|
| MOT test number | 611504849585 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-18 |

| MOT : | # 5 2023-10-18 11:19 | |
|-------|--|--|
| MOT | test number 708602632422 | |
| Resul | t × Failed | |
| Fail | Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) | |
| Fail | Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) | |
| Fail | Offside Rear Brake cable damaged (1.1.15 (a)) | |
| Fail | Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) | |
| Fail | Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) | |
| Fail | Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b)) | |

CarCheck.co.uk page 3/11



MOT #4 2022-09-26 14:07

MOT test number 166311702027

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Tyre pressure light on dash

Advice Nearside Rear Nail in tyre

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2021-09-28 14:15

MOT test number 382099741588

Result ✓ Passed

MOT #2 2021-01-28 16:41

MOT test number 956276314214

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2020-07-23 07:45

MOT test number 285720429568

Result

Passed

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 March |
|------------------|---------------------|
| Days left | 306 |
| MOT expiry date | 18 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | F |
| First licence fee (12 months) | £ 185,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| o mile motory | |
|--|-------------|
| For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report | |
| *************************************** | |
| | |
| *************************************** | |
| | |
| manage of the same | |
| | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this FIAT had different number plates. | |
| Number of plates | |
| Current registration | NK NK |
| Plate since | |
| Current registration | NK SIN |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 8/11



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Courte at Info | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2017-07-31 |
| Last registration | 2023-10-19 |
| Complete history | See info |



| Registration #1 | 2017-07-31 | 16 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-01-28 | 31.072 mi |
| Registration #3 | | 11.777 es |
| Registration #4 | 2021-09-28 | 33.205 mi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11,777 es |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | *** |
|----------------|-----------------|
| Adult | 66% |
| Children | 49% |
| Pedestrian | 53% |
| Safety systems | 27% |
| Overall rating | 52% |
| Video | see crash video |



Dimensions & weight

| Width | 1627 mm |
|---------------------|---------|
| Height | 1488 mm |
| Length | 3571 mm |
| Wheel base | 2300 mm |
| Kerb weight | 865 kg |
| Max. allowed weight | 1345 kg |

Additional information

| Fuel delivery | Multi-Point Injection |
|-----------------------------------|-----------------------|
| Number of doors | 3 |
| Number of seats | 4 |
| Number of axles Carcheck.co.uk | 2 page 11/11 |