





report date: 2024-03-28

General information

| Make | VAUXHALL |
|---------------------|-------------------|
| Model | CORSA ENERGY |
| Colour | Blue |
| Year of manufacture | 2019 |
| Top speed | 106 mph |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 89 BHP |
|----------------------|---------------------|
| Max. torque | 130 Nm at 4.000 rpm |
| Engine capacity | 1.398 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption combined | 39.8 mpg |
| CO2 emission | 150 g/km |
| CO2 label | F |



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-11-03


Pictures 30

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2024-11-01 |
|--------------------|------------|
| MOT pass rate | 60 % |
| MOT passed | 3 |
| Failed MOT tests | 2 |
| Total advice items | 4 |
| Total items failed | 3 |

| MOT #5 | | 2023-10-19 14:49 |
|-----------|---|------------------|
| MOT test | number | 804769500487 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-11-01 |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Tyre slightly damaged/cracking or perishing All four tyres (5.2.3 (d) (ii)) | |

| MOT #4 | 2023-10-19 14:06 | |
|--|------------------|--|
| MOT test number | 187705913199 | |
| Result | X Failed | |
| Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (| ii)) | |
| Advice Tyre slightly damaged/cracking or perishing All four tyres (5.2.3 (d) (ii)) | | |
| Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |

| MOT #3 | 2022-10-28 13:41 |
|-----------------|------------------|
| MOT test number | 251204467306 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



MOT #2 2021-11-02 20:18

MOT test number 703751243686

MOT #1 2021-11-02 18:48

MOT test number 798034335682

Result × Failed

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 January |
|------------------|-----------------------|
| Days left | 247 |
| MOT expiry date | 1 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | Н |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date


Category
Type

Damage 2

Category

Date

Туре



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner. | |
|--|-------------|
| ******** | |
| ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | |
| *************************************** | |
| 2000000 | |
| | |
| 200000000 | |
| Plate changes | More info > |
| See in this check if this VAUXHALL had different number plates. | |
| Number of plates | |
| Current registration | UK NE |
| Plate since | |
| Current registration | NK NA |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2019-01-28 |
| Last registration | 2023-10-19 |
| Complete history | See info |



| Registration #1 | 2019-01-28 | 25 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-11-02 | 2.595 mi |
| Registration #3 | 2021-11-02 | 2.605 mi |
| Registration #4 | | 77,777 66 |
| Registration #5 | | 11.777 es |
| Registration #6 | | 71.777 66 |
| Registration #7 | | 11,777 mi |

More info >

CarCheck.co.uk page 10/11



Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 79% |
| Children | 77% |
| Pedestrian | 71% |
| Safety systems | 56% |
| Overall rating | 72% |
| Video | see crash video |



Dimensions & weight

| Width | 1746 mm |
|---------------------|---------|
| Height | 1481 mm |
| Length | 4021 mm |
| Max. allowed weight | 1660 kg |

Additional information

| Number of seats | 5 |
|-----------------|---------------------|
| Number of axles | 2 |
| Engine number | B14XER -19UK1306LDD |

CarCheck.co.uk page 11/11