



RENAULT




report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT 111 EU4
Colour	Red
Year of manufacture	2006
Top speed	113 mph
0 - 60 mph	12.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	150 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	184 g/km
CO2 label	I







Internet history

Entry 1

Date	2021-06-23
Pictures	6
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-07-02
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	63
Total items failed	14

MOT #21	2021-07-03 11:41
MOT test number	558833607517
Result	✓ Passed
Next expiry date	2022-07-02

MOT #20	2020-09-16 11:04
MOT test number	967528105540
Result	✓ Passed

- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #19**

2020-09-09 14:41

MOT test number

639980872466

Result**✗ Failed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect headlamp lens defective (4.1.2 (c))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Brake performance not tested due to condition of front discs (1.2.1 (g))**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect headlamp lens defective (4.1.2 (c))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Offside Front Play in steering rack inner joint(s)



MOT #18

2019-09-19 11:31

MOT test number

102754625884

Result		✓ Passed
Advice	Offside Play in steering rack inner joint(s)	
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake discs in a poor state	
Advice	Number plates are cable tied different set numbers plates underneath	
Advice	Nearside Play in steering rack inner joint(s)	
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Smooth outside edge (5.2.3 (e))	
Advice	Nearside Rear Seat belt not checked as child seat fitted	

**MOT #17**

2019-09-11 09:12

MOT test number

450945953406

Result**✗ Failed**

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Play in steering rack inner joint(s)

Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Smooth outside edge (5.2.3 (e))

Advice Nearside Rear Seat belt not checked as child seat fitted

Advice Nearside Play in steering rack inner joint(s)

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Brake discs in a poor state

Advice Number plates are cable tied different set numbers plates underneath

Fail Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #16

2018-09-12 08:26

MOT test number

514000644499

Result**✓ Passed**

Advice Slight movement in inner rack joints

Advice Number plates are cable tied to another set

Advice Nearside Rear Tyre worn smooth on the outside edge

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Front and rear brake discs are in a poor state

**MOT #15** 2017-09-12 15:15**MOT test number** 485731769446**Result** ✓ Passed**Advice** Offside Rear Seat belt not checked as child seat fitted**Advice** Offside Slight movement in inner rack joint**Advice** Number plates are cabletied to a different set**MOT #14** 2017-09-11 11:29**MOT test number** 261101357354**Result** ✗ Failed**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Offside Slight movement in inner rack joint**Advice** Number plates are cabletied to a different set**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Advice** Offside Rear Seat belt not checked as child seat fitted**MOT #13** 2016-09-05 15:29**MOT test number** 509862621553**Result** ✓ Passed**Advice** Slight movement in O/S inner rack joint**Advice** Rear seat belts not checked as child seats fitted

**MOT #12** 2016-09-05 14:43**MOT test number** 382807092809**Result** ✗ Failed**Fail** Nearside Direction indicator adversely affected by the operation of another lamp (1.4.A.2h)**Advice** Rear seat belts not checked as child seats fitted**Fail** Offside Stop lamp adversely affected by the operation of another lamp (1.2.1f)**Advice** Slight movement in O/S inner rack joint**MOT #11** 2015-09-11 15:01**MOT test number** 307361089377**Result** ✓ Passed**Advice** Rear tyres are perished**MOT #10** 2014-09-08 15:04**MOT test number** 497461954205**Result** ✓ Passed**MOT #9** 2013-09-30 15:50**MOT test number** 276003373287**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Items removed from driver's view prior to test

**MOT #8** 2012-09-29 15:07**MOT test number** 189733272244**Result** ✓ Passed**Notice** Nail in offside rear tyre**MOT #7** 2012-09-29 15:07**MOT test number** 476583772203**Result** ✗ Failed**Notice** Nail in offside rear tyre**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #6** 2011-09-26 13:38**MOT test number** 928309761296**Result** ✓ Passed**MOT #5** 2011-09-26 09:57**MOT test number** 536449061273**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #4** 2010-10-01 15:29**MOT test number** 944234470241**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2009-10-23 14:33
MOT test number	804026799298
Result	✓ Passed

MOT #2	2009-10-23 14:33
MOT test number	111746799265
Result	✗ Failed
<div>Pass with rectification</div> Nearside Headlamp aim too low and too far to the left. (1.8)	

MOT #1	2008-11-12 10:54
MOT test number	713607718350
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 August 2022

✕
MOT

Expired:
2 July 2022

Tax status	Expired at 1 August 2022
Days left	638 days too late
MOT expiry date	2 July 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history


Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-10-23
Last registration	2021-07-03
Complete history	See info



Registration #1	2006-10-23	10 mi
Registration #2	2008-11-12	21.673 mi
Registration #3	2009-10-23	28.400 mi
Registration #4	2010-10-01	35.381 mi
Registration #5	2011-09-26	42.491 mi
Registration #6	2011-09-26	42.491 mi
Registration #7	2012-09-29	49.381 mi
Registration #8	2013-09-30	55.912 mi
Registration #9	2014-09-08	59.971 mi
Registration #10	2015-09-11	64.840 mi
Registration #11	2016-09-05	72.233 mi
Registration #12	2016-09-05	72.233 mi
Registration #13	2016-09-05	72.233 mi
Registration #14	2016-09-05	72.233 mi
Registration #15	2016-09-05	72.233 mi
Registration #16	2016-09-05	72.233 mi
Registration #17	2016-09-05	72.233 mi
Registration #18	2016-09-05	72.233 mi
Registration #19	2016-09-05	72.233 mi
Registration #20	2016-09-05	72.233 mi
Registration #21	2016-09-05	72.233 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2026 mm
Height	1458 mm
Length	4209 mm
Wheel base	2625 mm
Kerb weight	1205 kg
Max. allowed weight	1775 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D011354