



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE DCI 106 SCENIC
Colour	Blue
Year of manufacture	2007
Top speed	116 mph
0 - 60 mph	11.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	106 BHP
Max. torque	240 Nm at 2.000 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	60.1 mpg
CO2 emission	137 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-15
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-06-20
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	42
Total items failed	14

MOT #18 2021-06-14 10:47

MOT test number 598586014682

Result ✓ Passed

Next expiry date 2022-06-20

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Front Play in steering rack inner joint(s)

MOT #17 2021-06-09 12:12

MOT test number 642392184681

Result ✗ Failed

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Front Play in steering rack inner joint(s)

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #16** 2020-06-12 14:19**MOT test number** 229596677399**Result** ✓ Passed

- Advice** Play in steering rack inner joint(s)
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #15 2020-06-11 10:14**MOT test number** 282808234157**Result** ✗ Failed

- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Play in steering rack inner joint(s)
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #14 2019-06-21 12:35**MOT test number** 707781700731**Result** ✓ Passed

**MOT #13**

2019-06-13 09:37

MOT test number

843467988663

Result**✗ Failed**

- Fail** Electronic parking brake warning indicates a malfunction (1.1.6 (e))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Rear Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Play in steering rack inner joint(s)

MOT #12

2018-09-13 12:37

MOT test number

840314146788

Result**✓ Passed**

- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Play in steering rack inner joint(s)

MOT #11

2017-09-18 12:50

MOT test number

817771124639

Result**✓ Passed**

- Advice** Nearside Inner Ball joint has slight play on limit (2.2.B.1f)

MOT #10

2016-09-21 10:14

MOT test number

216484061361

Result**✓ Passed**

- Advice** Parking brake efficiency 17%

**MOT #9** 2015-09-09 12:16**MOT test number** 912162610046**Result** ✓ Passed**Advice** Advise rear child seat,s fitted at time of test**Advice** Nearside Rear Outer Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2015-09-09 12:16**MOT test number** 864108853988**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Outer Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Advise rear child seat,s fitted at time of test**MOT #7** 2014-09-22 12:13**MOT test number** 549535764297**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Under-trays fitted obscuring some underside components

**MOT #6** 2014-09-20 10:56**MOT test number** 475063564264**Result** ✗ Failed

- Notice** Under-trays fitted obscuring some underside components
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Fail** Nearside Front Ball joint has excessive play (2.2.B.1f)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

MOT #5 2014-07-16 10:39**MOT test number** 289357394442**Result** ✓ Passed

- Notice** Park brake warning faulty

MOT #4 2013-07-22 09:48**MOT test number** 359603503448**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Dashboard shows parkbrake fault
- Notice** Headlamp/indicator switch mechanism worn
- Notice** Play steering nearside

**MOT #3** 2012-07-25 09:45**MOT test number** 869217702244**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #2** 2011-07-28 13:58**MOT test number** 337279301427**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Bottom engine cover fitted, Can't check for corrosion**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2010-07-31 14:49**MOT test number** 392262810249**Result** ✓ Passed**Notice** Electronic brake fault warning light on**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
22 November 2021

X

MOT

Expired:
20 June 2022

Tax status	Expired at 22 November 2021
Days left	889 days too late
MOT expiry date	20 June 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-03-29
Current registration	*****
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-09-03
Last registration	2021-06-14
Complete history	See info



Registration #1	2007-09-03	25 mi
Registration #2	2010-07-31	49.058 mi
Registration #3	2011-07-28	52.700 mi
Registration #4	2012-07-25	56.963 mi
Registration #5	2013-07-22	48.143 mi
Registration #6	2014-07-16	64.673 mi
Registration #7	2014-09-20	65.511 mi
Registration #8	2014-09-22	65.511 mi
Registration #9	2015-09-09	70.195 mi
Registration #10	2016-09-09	75.377 mi
Registration #11	2017-09-09	80.559 mi
Registration #12	2018-09-09	85.741 mi
Registration #13	2019-09-09	90.923 mi
Registration #14	2020-09-09	96.105 mi
Registration #15	2021-09-09	101.287 mi
Registration #16	2022-09-09	106.469 mi
Registration #17	2023-09-09	111.651 mi
Registration #18	2024-09-09	116.833 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1620 mm
Length	4259 mm
Wheel base	2685 mm
Kerb weight	1200 kg
Max. allowed weight	1945 kg

Additional information

Fuel tank capacity	49 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	D368817
---------------	---------