



report date: 2024-03-28

General information

Make	VAUXHALL
Model	MOVANO F3500 L2H2 P/V CDTi
Colour	White
Year of manufacture	2013
Top speed	134 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	285 Nm at 1.250 rpm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	37.7 mpg
Consumption combined	34.0 mpg
CO2 emission	205 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-11-03
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-17
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	13
Total items failed	2

MOT #10 2023-09-26 09:41

MOT test number 550373703441

Result ✓ Passed

Next expiry date 2024-10-17

Advice Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Outer Integral body structure is deformed but structural rigidity is not significantly reduced outer sill damaged (6.1.1 (a) (i))

MOT #9 2022-09-22 13:59

MOT test number 981315988268

Result ✓ Passed**Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Nail in tyre**Advice** Nearside Outer Integral body structure is deformed but structural rigidity is not significantly reduced Sill (6.1.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2021-09-28 13:04**MOT test number** 729367307390**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2021-09-28 13:04**MOT test number** 453877670311**Result** ✗ Failed**Pass with rectification** Central Rear Stop lamp(s) emits other than a steady red light (4.3.3 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2020-10-08 13:48**MOT test number** 529700878037**Result** ✓ Passed**MOT #5** 2020-10-08 13:48**MOT test number** 730398301893**Result** ✗ Failed**Pass with rectification** Offside Front Inner Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #4** 2019-10-10 13:21**MOT test number** 147370593641**Result** ✓ Passed**MOT #3** 2018-10-02 13:11**MOT test number** 870297425561**Result** ✓ Passed**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))



MOT #2	2017-10-03 14:58
MOT test number	831574629793
Result	✓ Passed
Advice	Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

MOT #1	2016-10-07 14:13
MOT test number	243689782540
Result	✓ Passed
Advice	Electrical wiring damaged, but not likely to become detached brake light switch (1.9.2b)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
17 October 2024

Tax status		Valid until 1 November
Days left		186
MOT expiry date		17 October 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-10-18
Last registration	2023-09-26
Complete history	See info



Registration #1	2013-10-18	6 mi
Registration #2	2016-10-07	15.872 mi
Registration #3	2017-10-03	16.670 mi
Registration #4	2018-10-02	17.125 mi
Registration #5	2019-10-10	17.446 mi
Registration #6	2020-10-08	18.070 mi
Registration #7	2023-09-26	20.277 mi
Registration #8	2023-09-26	20.277 mi
Registration #9	2023-09-26	20.277 mi
Registration #10	2023-09-26	20.277 mi
Registration #11	2023-09-26	20.277 mi
Registration #12	2023-09-26	20.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2470 mm
Height	2500 mm
Length	5548 mm
Kerb weight	1890 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	M9T -C064461 LWK