



PEUGEOT



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | PEUGEOT |
| Model | RCZ HDI GT |
| Colour | Grey |
| Year of manufacture | 2011 |
| Top speed | 137 mph |
| 0 - 60 mph | 8.7 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 163 BHP |
| Max. torque | 340 Nm at 2.000 rpm |
| Engine capacity | 1.997 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 41.5 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 53.3 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-12-05 |
| Pictures | 18 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-15 |
| MOT pass rate | 69 % |
| MOT passed | 11 |
| Failed MOT tests | 5 |
| Total advice items | 49 |
| Total items failed | 14 |

| | |
|------------------|---|
| MOT #16 | 2023-06-26 10:01 |
| MOT test number | 250711728766 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-15 |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |

| | |
|-----------------|---|
| MOT #15 | 2022-07-16 09:00 |
| MOT test number | 359137284842 |
| Result | ✓ Passed |
| Advice | Front Hydraulic leak, but not excessive (8.4.1 (a) (i)) |

| | |
|-----------------|--|
| MOT #14 | 2022-07-12 12:08 |
| MOT test number | 272597013750 |
| Result | ✗ Failed |
| Advice | Front Hydraulic leak, but not excessive (8.4.1 (a) (i)) |
| Fail | Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d)) |
| Fail | Nearside Rear Outer Tyre has ply or cords exposed cut to sidewall. 235/40 19 (5.2.3 (d) (ii)) |
| Fail | Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b)) |

**MOT #13**

2021-08-19 10:45

MOT test number

613810996625

Result

✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Engine covers and under trays fitted

MOT #12

2021-07-19 08:22

MOT test number

639900606270

Result

✗ Failed

- Fail** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front Suspension component ball joint has slight play (5.3.4 (a) (i))
- Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Brake lever has insufficient reserve travel (1.1.2 (a))
- Fail** Oil leaking excessively from engine (8.4.1 (a) (i))
- Fail** Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Headlamp aim too high (4.1.2 (a))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #11**

2020-08-03 16:19

MOT test number

225824650688

Result

✓ Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10**

2019-07-29 14:14

MOT test number

240122670383

Result

✓ Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #9**

2018-08-08 14:47

MOT test number

336937733000

Result

✓ Passed

**MOT #8** 2018-05-08 11:10**MOT test number** 670387035702**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Lower Bonded suspension unit deteriorated but can function as intended (2.4.F.3)
- Advice** Offside Rear Nail in tyre
- Advice** Nearside Front Lower Bonded suspension unit deteriorated but can function as intended (2.4.F.3)

MOT #7 2017-08-07 11:10**MOT test number** 686489125979**Result** ✓ Passed**MOT #6** 2016-08-13 10:55**MOT test number** 138174472373**Result** ✓ Passed

- Advice** Both front wipers poor
- Advice** Both rear tyre about 3mm -nearside rear wearing uneven inner edge in places
- Advice** Offside Rear brake pads 2000 miles

MOT #5 2016-08-12 15:08**MOT test number** 436406039193**Result** ✗ Failed

- Advice** Both front wipers poor
- Advice** Offside Rear brake pads 2000 miles
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Both rear tyre about 3mm -nearside rear wearing uneven inner edge in places



| | |
|-----------------|---|
| MOT #4 | 2015-05-19 16:52 |
| MOT test number | 688189735146 |
| Result | ✓ Passed |
| Advice | Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a) |
| Notice | N/s rear outer wall damaged |
| Notice | Front discs worn |
| Advice | Parking brake lever has little reserve travel (3.1.6b) |

| | |
|-----------------|---|
| MOT #3 | 2015-05-19 10:59 |
| MOT test number | 185079835190 |
| Result | ✗ Failed |
| Fail | Front Brake pad(s) less than 1.5 mm thick (3.5.1g) |
| Notice | N/s rear outer wall damaged |
| Advice | Parking brake lever has little reserve travel (3.1.6b) |
| Notice | Front discs worn |
| Advice | Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a) |



MOT #2

2014-05-21 11:34

MOT test number

185061044195

Result

✓ Passed

- Notice

Items removed from driver's view prior to test
- Notice

N/s/r tyre has damage to side-wall
- Advice

Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice

Engine covers fitted obscuring some components in the engine bay
- Notice

N/s/f tyre has damage to side-wall
- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice

Under-trays fitted obscuring some underside components

MOT #1

2014-05-20 13:12

MOT test number

249500844125

Result

✗ Failed

- Advice

Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice

N/s/r tyre has damage to side-wall
- Notice

Engine covers fitted obscuring some components in the engine bay
- Fail

Exhaust emits an excessive level of metered smoke (7.4.B.3a)
- Notice

N/s/f tyre has damage to side-wall
- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice

Under-trays fitted obscuring some underside components
- Notice

Items removed from driver's view prior to test



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
15 July 2024

| | |
|------------------|---------------------------------|
| Tax status | Valid until 1 May |
| Days left | 2 |
| MOT expiry date | 15 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | KY11UNU |
| Plate since | 2024-03-29 |
| Current registration | KY11UNU |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 18 |
| First mileage registration | 2011-06-01 |
| Last registration | 2023-06-26 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2011-06-01 | 23 mi |
| Registration #2 | 2014-05-20 | 32.065 mi |
| Registration #3 | 2014-05-21 | 32.074 mi |
| Registration #4 | 2015-05-19 | 42.060 mi |
| Registration #5 | 2015-05-19 | 42.060 mi |
| Registration #6 | 2016-08-12 | 44.738 mi |
| Registration #7 | 2016-08-13 | 44.740 mi |
| Registration #8 | 2017-08-07 | 58.495 mi |
| Registration #9 | 2018-05-08 | 67.199 mi |
| Registration #10 | 2019-05-20 | 75.277 mi |
| Registration #11 | 2019-05-20 | 75.277 mi |
| Registration #12 | 2019-05-20 | 75.277 mi |
| Registration #13 | 2019-05-20 | 75.277 mi |
| Registration #14 | 2019-05-20 | 75.277 mi |
| Registration #15 | 2019-05-20 | 75.277 mi |
| Registration #16 | 2019-05-20 | 75.277 mi |
| Registration #17 | 2019-05-20 | 75.277 mi |
| Registration #18 | 2019-05-20 | 75.277 mi |

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 82% |
| Children | 81% |
| Pedestrian | 53% |
| Safety systems | 83% |
| Overall rating | 76% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2107 mm |
| Height | 1352 mm |
| Length | 4290 mm |
| Kerb weight | 1445 kg |
| Max. allowed weight | 1825 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Direct Injection |
| Number of doors | 2 |
| Number of seats | 4 |
| Number of axles | 2 |

Engine number

DYXR4007019