



AV63WUR

report date: 2024-03-28

General information

Make	FIAT
Model	500 C S
Colour	White
Year of manufacture	2013
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	58.9 mpg
CO2 emission	113 g/km
CO2 label	C







Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2023-05-31
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	13
Total items failed	1

MOT #10 2023-11-27 15:33

MOT test number 784425047847

Result ✗ Failed

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MAJOR Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

DANGEROUS Offside Front Inner Tyre tread depth below requirements of 1.6mm very heavy wear on inner edge (5.2.3 (e))

MAJOR Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MAJOR Brake lever has abnormal movement of levers indicating excessive wear or maladjustment (1.1.15 (f))

MAJOR Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #9 2022-06-01 10:32

MOT test number 767919055948

Result ✓ Passed

**MOT #8** 2022-05-31 10:45**MOT test number** 577266446577**Result** ✗ Failed**MAJOR** Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))**MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #7** 2021-05-18 08:00**MOT test number** 360012932662**Result** ✓ Passed**MOT #6** 2021-01-06 13:06**MOT test number** 338626277480**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing inner wall (5.2.3 (d) (ii))**MOT #5** 2021-01-06 13:06**MOT test number** 902716964044**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing inner wall (5.2.3 (d) (ii))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #4** 2020-02-03 12:34**MOT test number** 821539011318**Result** ✓ Passed**MOT #3** 2019-02-27 10:20**MOT test number** 252154794412**Result** ✓ Passed



MOT #2	2017-11-30 09:23
MOT test number	776059700508
Result	✓ Passed

MOT #1	2016-12-20 15:40
MOT test number	936516181011
Result	✓ Passed

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✗
MOT

Expired:
31 May 2023

Tax status	Valid until 1 May
Days left	2
MOT expiry date	31 May 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-12-20
Last registration	2023-11-27
Complete history	See info



Registration #1	2013-12-20	16 mi
Registration #2	2016-12-20	22.155 mi
Registration #3	2017-11-30	28.340 mi
Registration #4	2019-02-27	40.966 mi
Registration #5	2020-02-03	80.163 mi
Registration #6	2021-01-06	53.927 mi
Registration #7	2022-01-06	55.277 mi
Registration #8	2022-01-06	55.277 mi
Registration #9	2022-01-06	55.277 mi
Registration #10	2022-01-06	55.277 mi
Registration #11	2022-01-06	55.277 mi
Registration #12	2022-01-06	55.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	0560529