





report date: 2024-03-29

General information

Make	KIA
Model	RIO 1
Colour	White
Year of manufacture	2010
Top speed	108 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	125 Nm at 4.700 rpm
Engine capacity	1.399 сс
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-06-14

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-11-25
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	24
Total items failed	4

MOT #14		2023-11-07 16:39
MOT test	number	728658667135
Result		✓ Passed
Next expi	ry date	2024-11-25
Advice	Central Front Exhaust mounting defective (6.1.2 (a))	
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Rear axle corroded	
Advice	Central Rear Exhaust mounting defective (6.1.2 (a))	

MOT #13		2022-11-10 09:21
MOT test	number	143577607752
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened x2	corroded (1.1.14 (a) (ii))
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush perished (5.3.4 (a) (i))		
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e	e))
Advice	Central Exhaust mounting defective (6.1.2 (a))	
Advice bush peris	Offside Front Suspension arm pin or bush worn but not resulting in excellent (5.3.4 (a) (i))	essive movement front

CarCheck.co.uk page 3/13



MOT #12

MOT test number

Result

Advice Central Exhaust mounting defective (6.1.2 (a))

MOT test number

134003577848

Result

Fail Brake pipe excessively corroded x2 front to rear (1.1.11 (c))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (iii))

Advice Central Exhaust mounting defective (6.1.2 (a))

 MOT #10
 2020-11-17 09:42

 MOT test number
 274769888146

 Result
 ✓ Passed

 MOT #9
 2019-11-26 13:57

 MOT test number
 915760552978

 Result
 ✓ Passed

 MOT #8
 2019-11-26 10:01

MOT #8

MOT test number

Result

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 4/13



MOT #7 2018-11-21 12:23

MOT test number 639375504589

Result ✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #6 2017-11-22 13:45

MOT test number 315508805049

Result
✓ Passed

MOT #5 2016-11-25 17:24

MOT test number 728096224538

Result ✓ Passed

MOT #4 2015-10-21 09:22

MOT test number 842598114095

Result ✓ Passed

Advice Nearside Rear tyre worn on outer edge

MOT #3 2014-06-14 12:15

MOT test number 885945064120

Result \(\sqrt{Passed} \)

Notice Vehicle's internal headlight adjuster altered to recheck lights

Notice Items removed from driver's view prior to test

Notice Both rear tyres sidewalls cracked

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



MOT #2 2014-06-14 12:15 **MOT test number** 647935164117 Result **X** Failed **Notice** Items removed from driver's view prior to test Notice Both rear tyres sidewalls cracked Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) Notice Vehicle's internal headlight adjuster altered to recheck lights Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #1	2013-06-10 11:47
MOT test number	268911163445
Result	✓ Passed

CarCheck.co.uk page 6/13





Tax & MOT check





Expires: 25 November 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	25 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-


CarCheck.co.uk page 7/13



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>have the current and the full report have the current and the full report have the current and the full report have the current and the full report <u>have the current and the full report have the current and previous owner(s) have this KIA? How many owners did</u></u>		

THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDR		

	More info >	
Plate changes		
See in this check if this KIA had different number plates.		
Number of plates		9
Current registration	AR SIE	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-06-21
Last registration	2023-11-07
Complete history	See info



Registration #1	2010-06-21	14 mi
Registration #2	2013-06-10	15.948 mi
Registration #3	2014-06-14	21.342 mi
Registration #4	2015-10-21	28.504 mi
Registration #5	2016-11-25	34.344 mi
Registration #6	2017-11-22	38.449 mi
Registration #7	2018-11-21	41.146 mi
Registration #8	2019-11-26	46.070 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		D.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1470 mm
Length	3990 mm
Wheel base	2500 mm
Kerb weight	1244 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Engine number

G4EE9H280020