



HONDA



report date: 2024-03-29

General information

Make	HONDA
Model	CR-Z I-VTEC IMA SPORT
Colour	Black
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	145 Nm at 4.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	117 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-10-26
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-08
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	16
Total items failed	3

MOT #12	2023-12-08 18:01
MOT test number	330186382370
Result	✓ Passed
Next expiry date	2024-12-08
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Minor	Front Suspension arm ball joint dust cover severely deteriorated Both (5.3.4 (b) (i))
Minor	Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt Both (2.1.3 (g) (i))

MOT #11	2023-12-07 14:05
MOT test number	896003921556
Result	✗ Failed
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Minor	Front Suspension arm ball joint dust cover severely deteriorated Both (5.3.4 (b) (i))
Fail	Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Minor	Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt Both (2.1.3 (g) (i))

**MOT #10** 2022-12-09 15:50**MOT test number** 366923743623**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear seat belts are not tested (items)**Minor** Front Suspension arm ball joint dust cover severely deteriorated bothside (5.3.4 (b) (i))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #9** 2021-11-15 11:04**MOT test number** 105566951198**Result** ✓ Passed**MOT #8** 2020-12-09 17:20**MOT test number** 606698580655**Result** ✓ Passed**Advice** Parking brake effort low, on 16% limit**MOT #7** 2019-09-04 13:18**MOT test number** 249031549636**Result** ✓ Passed**MOT #6** 2019-09-03 09:41**MOT test number** 673398160438**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin worn low (1.1.13 (a) (ii))**Fail** Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt both links upper gaiters split open (5.3.4 (b) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened outer face corroded (1.1.14 (a) (ii))

**MOT #5** 2018-06-13 15:40**MOT test number** 695773153695**Result** ✓ Passed**MOT #4** 2018-06-13 15:40**MOT test number** 460392115995**Result** ✗ Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively rubber split (3.4 (b) (ii))

MOT #3 2017-06-20 08:54**MOT test number** 271783519621**Result** ✓ Passed

Advice Front brake pads worn very low just passing

MOT #2 2016-04-05 14:47**MOT test number** 574230967432**Result** ✓ Passed

Advice Both front tyres worn on inner edges

MOT #1 2015-03-10 10:10**MOT test number** 589089265066**Result** ✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
8 December 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	8 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	C
Single payment (12 months)	£ 25,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 26,25,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-05
Last registration	2023-12-08
Complete history	See info



Registration #1	2012-03-05	7 mi
Registration #2	2015-03-10	21.156 mi
Registration #3	2016-04-05	26.518 mi
Registration #4	2017-06-20	36.880 mi
Registration #5	2018-06-13	51.684 mi
Registration #6	2018-06-13	51.684 mi
Registration #7	2019-09-03	70.692 mi
Registration #8	2020-09-03	91.277 mi
Registration #9	2021-09-03	91.277 mi
Registration #10	2022-09-03	91.277 mi
Registration #11	2023-09-03	91.277 mi
Registration #12	2023-09-03	91.277 mi
Registration #13	2023-09-03	91.277 mi
Registration #14	2023-09-03	91.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	80%
Pedestrian	71%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2014 mm
Height	1395 mm
Length	4080 mm
Wheel base	2425 mm
Kerb weight	1198 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	LEA1 1017966