



report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 DSTYLE PLUS
Colour	White
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.200 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.4 mpg
CO2 emission	136 g/km
CO2 label	E





Internet history

Entry 2

Date	2023-06-14
Pictures	0
Listing price	<a href="#">View report</a>

source: carcraft.co.uk

Entry 1

Date	2021-02-28
Pictures	2
Listing price	<a href="#">View report</a>



source: yesauto.com



MOT history

MOT expiry date	2025-03-18
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	25
Total items failed	10

MOT #14	2024-03-15 10:51
MOT test number	899558676605
Result	✓ Passed
Next expiry date	2025-03-18
Advice	Front Direction indicator slightly discoloured Both sides (4.4.3 (a))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
Advice	Front Shock absorbers has a reduced damping effect Both sides (5.3.2 (d))
Advice	Front Inner Brake pad(s) wearing thin Both sides inner pad (1.1.13 (a) (ii))

**MOT #13**

2024-03-14 10:59

**MOT test number**

472615703201

**Result**

✗ Failed

- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Direction indicator slightly discoloured Both sides (4.4.3 (a))
- Advice** Front Inner Brake pad(s) wearing thin Both sides inner pad (1.1.13 (a) (ii))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Front Shock absorbers has a reduced damping effect Both sides (5.3.2 (d))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #12**

2023-03-13 10:19

**MOT test number**

543692879548

**Result**

✓ Passed

- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #11**

2022-03-15 09:00

**MOT test number**

338239381644

**Result**

✓ Passed

**MOT #10**

2021-03-19 13:02

**MOT test number**

470641657442

**Result**

✓ Passed

**MOT #9** 2021-03-18 13:26**MOT test number** 213820171393**Result** ✗ Failed**Fail** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Front Exhaust has a minor leak of exhaust gases Flexy section (6.1.2 (a))**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Rear Exhaust system insecure Hanger (6.1.2 (a))**MOT #8** 2020-07-15 11:03**MOT test number** 461210260547**Result** ✓ Passed**Advice** Exhaust system corroded nail in osr tyre**MOT #7** 2019-05-25 08:07**MOT test number** 548511068392**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases flexi section split (6.1.2 (a))**MOT #6** 2019-05-25 07:54**MOT test number** 801188135904**Result** ✗ Failed**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases flexi section split (6.1.2 (a))**MOT #5** 2018-05-21 15:44**MOT test number** 250539176851**Result** ✓ Passed

**MOT #4** 2018-05-19 10:04**MOT test number** 588878416168**Result** ✗ Failed**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Rear Exhaust system not adequately supported belly clamp split (7.1.1)**Advice** Nearside Front Outer Brake pad(s) wearing thin pads on 2mm (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit on 3mm (4.1.E.1)**MOT #3** 2017-05-22 15:19**MOT test number** 463753212164**Result** ✓ Passed**Advice** Rear discs corroding**MOT #2** 2017-05-22 10:05**MOT test number** 119263296270**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Rear discs corroding**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2016-05-19 08:50**MOT test number** 397075594865**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
18 March 2025

Tax status	Valid until 1 July
Days left	64
MOT expiry date	18 March 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-05-28
Last registration	2024-03-15
Complete history	<a href="#">See info</a>



Registration #1	2013-05-28	19 mi
Registration #2	2016-05-19	16.499 mi
Registration #3	2017-05-22	20.649 mi
Registration #4	2017-05-22	20.650 mi
Registration #5	2018-05-19	25.799 mi
Registration #6	2018-05-21	25.834 mi
Registration #7	2019-05-25	29.912 mi
Registration #8	2019-05-25	29.912 mi
Registration #9	2020-07-15	32.592 mi
Registration #10	2020-05-20	35.377 mi
Registration #11	2020-05-20	35.377 mi
Registration #12	2020-05-20	35.377 mi
Registration #13	2020-05-20	35.377 mi
Registration #14	2020-05-20	35.377 mi
Registration #15	2020-05-20	35.377 mi
Registration #16	2020-05-20	35.377 mi
Registration #17	2020-05-20	35.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1147 kg
Max. allowed weight	1554 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FHCA1844795