



report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT SZ2
Colour	White
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	91 BHP
Max. torque	116 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	48.7 mpg



LABEL UNKNOWN

**MOT history**

MOT #14	2022-03-30 11:25
MOT test number	399809862125
Result	✓ Passed
Next expiry date	2023-03-29
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush Perished (5.3.4 (a) (i))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush Perished (5.3.4 (a) (i))	

MOT #13	2022-03-28 10:09
MOT test number	843843572020
Result	✗ Failed
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush Perished (5.3.4 (a) (i))	
Fail Brake lever has insufficient reserve travel (1.1.2 (a))	
Fail Offside Headlamp aim too high (4.1.2 (a))	
Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush Perished (5.3.4 (a) (i))	

MOT #12	2021-03-24 17:13
MOT test number	112941542483
Result	✓ Passed
Minor Nearside Front Anti-roll bar ball joint dust cover severely deteriorated Upper & Lower (5.3.4 (b) (i))	

MOT #11	2020-02-12 16:40
MOT test number	505749042082
Result	✓ Passed

**MOT #10** 2020-02-12 14:29**MOT test number** 338353973309**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #9** 2019-03-22 13:19**MOT test number** 473641230033**Result** ✓ Passed**MOT #8** 2019-03-14 10:35**MOT test number** 818423492160**Result** ✗ Failed**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #7** 2018-03-19 12:03**MOT test number** 947376228581**Result** ✓ Passed**MOT #6** 2018-03-13 14:33**MOT test number** 598071665373**Result** ✗ Failed**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Rear Brakes imbalanced across an axle (3.7.B.5b)**MOT #5** 2017-03-08 10:31**MOT test number** 933656863025**Result** ✓ Passed



MOT #4	2016-03-14 14:37
MOT test number	258135947363
Result	✓ Passed
MOT #3	2015-03-11 11:28
MOT test number	297250275065
Result	✓ Passed
MOT #2	2014-03-11 10:41
MOT test number	476070174037
Result	✓ Passed
MOT #1	2013-03-08 10:36
MOT test number	755547963065
Result	✓ Passed



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	WJ10PGU
Plate since	2019-03-29
Current registration	WJ10PGU
Plate since	2019-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-15
Last registration	2022-03-30
Complete history	See info



Registration #1	2010-03-15	16 mi
Registration #2	2013-03-08	28.880 mi
Registration #3	2014-03-11	40.913 mi
Registration #4	2015-03-11	51.802 mi
Registration #5	2016-03-14	63.375 mi
Registration #6	2017-03-08	75.433 mi
Registration #7	2018-03-13	85.183 mi
Registration #8	2018-03-19	85.274 mi
Registration #9	2019-03-20	95.377 mi
Registration #10	2019-03-20	95.377 mi
Registration #11	2019-03-20	95.377 mi
Registration #12	2019-03-20	95.377 mi
Registration #13	2019-03-20	95.377 mi
Registration #14	2019-03-20	95.377 mi
Registration #15	2019-03-20	95.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1590 mm
Length	3760 mm
Wheel base	2380 mm
Kerb weight	970 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	M13A-2226353