



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY GHIA
Colour	Silver
Year of manufacture	2009
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	190 Nm at 1.750 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.2 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.4 mpg
CO2 emission	197 g/km
CO2 label	J







Internet history

Entry 1

Date	2021-07-15
Pictures	13
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-06-24
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	40
Total items failed	2

## MOT #13 2023-06-14 10:25

MOT test number 120896816108

Result ✓ Passed

Next expiry date 2024-06-24

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Rear Tyre edge worn bald and 3mm approx..

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Offside Rear Inner Tyre edge worn bald

## MOT #12 2023-06-14 10:25

MOT test number 258376905023

Result ✗ Failed

**Advice** Nearside Rear Tyre edge worn bald and 3mm approx..

**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Rear Inner Tyre edge worn bald

**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #11**

2022-06-14 10:48

**MOT test number**

380568802053

**Result**

✓ Passed

**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**MOT #10**

2021-06-19 11:50

**MOT test number**

844957183607

**Result**

✓ Passed

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge And out of shape (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge And out of shape (5.2.3 (e))

**MOT #9** 2020-06-17 09:29**MOT test number** 103742930465**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2019-06-19 08:51**MOT test number** 737027477697**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #7** 2018-06-19 10:58**MOT test number** 971113176828**Result** ✓ Passed**MOT #6** 2017-06-13 12:00**MOT test number** 127286135601**Result** ✓ Passed

- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2016-06-14 10:02**MOT test number** 632122733799**Result** ✓ Passed**Advice** Both rear tyres worn low on inner edges**Advice** Both front tyres worn low on outside edges**Advice** Nearside Rear tyre has staple in it**MOT #4** 2015-06-16 10:16**MOT test number** 239177565160**Result** ✓ Passed**Notice** 2 x nails in offside rear tyre**MOT #3** 2014-06-14 10:44**MOT test number** 267375164186**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-06-25 15:33**MOT test number** 537686773158**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-06-23 09:45**MOT test number** 699625472183**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
24 June 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	34
<b>MOT expiry date</b>	24 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-05-12
Last registration	2023-06-14
Complete history	<a href="#">See info</a>



Registration #1	2009-05-12	19 mi
Registration #2	2012-06-23	21.832 mi
Registration #3	2013-06-25	30.569 mi
Registration #4	2014-06-14	41.061 mi
Registration #5	2015-06-16	48.640 mi
Registration #6	2016-06-14	55.536 mi
Registration #7	2017-06-13	64.803 mi
Registration #8	2018-06-19	75.558 mi
Registration #9	2019-06-20	75.558 mi
Registration #10	2019-06-20	75.558 mi
Registration #11	2019-06-20	75.558 mi
Registration #12	2019-06-20	75.558 mi
Registration #13	2019-06-20	75.558 mi
Registration #14	2019-06-20	75.558 mi
Registration #15	2019-06-20	75.558 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Max. allowed weight	2415 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2

**Engine number**

8T20562