



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D5 SE LUX V50
Colour	Black
Year of manufacture	2008
Top speed	140 mph
0 - 60 mph	7.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	180 BHP
Max. torque	350 Nm at 3.250 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.8 mpg
CO2 emission	166 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-09-05
Pictures	23
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-09-04
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-05
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	21
Total items failed	16

MOT #20	2023-10-04 14:08
MOT test number	584584141893
Result	✓ Passed
Next expiry date	2024-10-05
Advice	Rear shock- absorber bump stops deteriorated
Advice	Nearside Front tyre worn inner & outer edges

MOT #19	2023-10-03 09:17
MOT test number	609623250830
Result	✗ Failed
Fail	Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Front Headlamp aim too low (4.1.2 (a))
Advice	Rear shock- absorber bump stops deteriorated
Fail	Fuel system component leaking from fuel filter (6.1.3 (b) (i))
Fail	Offside Rear Wheel bearing so rough it is likely to overheat or break up (5.1.3 (b) (ii))
Fail	Nearside Front Headlamp aim too low (4.1.2 (a))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Front tyre worn inner & outer edges

**MOT #18** 2022-10-04 09:46**MOT test number** 680188102228**Result** ✓ Passed**MOT #17** 2022-10-04 09:46**MOT test number** 578305926313**Result** ✗ Failed**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**MOT #16** 2021-09-15 10:33**MOT test number** 187641136300**Result** ✓ Passed**MOT #15** 2021-09-04 16:31**MOT test number** 140699433027**Result** ✗ Failed**Fail** Exhaust diesel particulate filter shows evidence of tampering. (8.2.2.1 (c))**Advice** Front Tyre worn close to legal limit/worn on edge Both Sides (5.2.3 (e))**MOT #14** 2020-10-06 12:37**MOT test number** 377459816806**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))

**MOT #13**

2020-10-05 10:37

MOT test number

665884536786

Result**✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))**Fail** Brake pedal anti-slip provision missing (1.1.2 (c))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))**Fail** Offside Front Road wheel fixing missing nut missing (5.2.1 (a) (i))**MOT #12**

2019-04-06 08:40

MOT test number

716259916057

Result**✓ Passed****MOT #11**

2018-04-11 15:21

MOT test number

648639437398

Result**✓ Passed****MOT #10**

2018-04-11 15:21

MOT test number

948790315565

Result**✗ Failed****Pass with rectification** Nearside Rear Tyre(s) incorrect because tyres with different structures are fitted across the same axle (4.1.A.2a)



MOT #9	2017-04-12 11:51
MOT test number	116763971076
Result	✓ Passed
Advice	Engine and sill areas not fully checked due to covers fitted

MOT #8	2017-04-07 13:13
MOT test number	229414937421
Result	✗ Failed
Advice	Engine and sill areas not fully checked due to covers fitted
Fail	Offside Front coil spring broken (2.4.C.1a)

MOT #7	2016-03-21 15:12
MOT test number	740079197899
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6	2015-04-10 16:24
MOT test number	109980205167
Result	✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #5	2014-04-08 11:12
MOT test number	608888494007
Result	✓ Passed
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)



MOT #4	2013-04-09 15:30
MOT test number	125959193057
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3	2012-04-11 10:51
MOT test number	998062402121
Result	✓ Passed

MOT #2	2011-03-04 09:57
MOT test number	658343261062
Result	✓ Passed

MOT #1	2011-03-03 14:40
MOT test number	118212761089
Result	✗ Failed
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Fail	Nearside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
5 October 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	5 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-03-20
Last registration	2023-10-04
Complete history	See info



Registration #1	2008-03-20	10 mi
Registration #2	2011-03-03	57.542 mi
Registration #3	2011-03-04	57.542 mi
Registration #4	2012-04-11	72.593 mi
Registration #5	2013-04-09	76.631 mi
Registration #6	2014-04-08	80.526 mi
Registration #7	2015-04-10	87.003 mi
Registration #8	2016-03-21	93.030 mi
Registration #9	2017-04-07	100.000 mi
Registration #10	2017-04-12	100.021 mi
Registration #11	2018-04-11	106.069 mi
Registration #12	2018-04-11	106.069 mi
Registration #13	2019-04-11	112.117 mi
Registration #14	2019-04-11	112.117 mi
Registration #15	2019-04-11	112.117 mi
Registration #16	2019-04-11	112.117 mi
Registration #17	2019-04-11	112.117 mi
Registration #18	2019-04-11	112.117 mi
Registration #19	2019-04-11	112.117 mi
Registration #20	2019-04-11	112.117 mi
Registration #21	2019-04-11	112.117 mi
Registration #22	2019-04-11	112.117 mi
Registration #23	2019-04-11	112.117 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1552 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	591562