



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 E4 D SE V50
Colour	Black
Year of manufacture	2006
Top speed	130 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	154 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-10-11
Pictures	30
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-12
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	24
Total items failed	3

MOT #18	2023-09-13 13:08
MOT test number	529554251396
Result	✓ Passed
Next expiry date	2024-09-12
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2022-07-07 12:50
MOT test number	579715870139
Result	✓ Passed
Advice	Exhaust system in poor condition

MOT #16	2022-06-24 13:15
MOT test number	695478382879
Result	✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Exhaust system in poor condition

**MOT #15** 2021-07-12 11:57**MOT test number** 282350520056**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2020-07-14 14:13**MOT test number** 496898130646**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Part of the exhaust system has slightly deteriorated**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13** 2019-07-18 10:17**MOT test number** 765485464676**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Part of the exhaust has slightly deteriorated**MOT #12** 2018-07-20 15:17**MOT test number** 666118529040**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Wiper blades streaky but not effecting drivers view of the road**Advice** Offside Rear Tyre slightly out of shape on inner edge**Advice** Rear Bump stops deteriorated

**MOT #11** 2017-09-06 12:43**MOT test number** 276121890918**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #10** 2017-09-06 09:09**MOT test number** 682450776768**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm has excessive play in a pin/bush (2.4.G.2)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2016-08-23 14:12**MOT test number** 845909438473**Result** ✓ Passed**Advice** BOTH FRONT LOWER SUSPENION ARMS,REAR BUSHES STARTING TO DELAMINATE....**Advice** FRONT TYRES WEARING INNER EDGES**MOT #8** 2015-09-07 14:17**MOT test number** 418668975314**Result** ✓ Passed**MOT #7** 2014-09-03 13:57**MOT test number** 437666244291**Result** ✓ Passed

**MOT #6** 2013-09-04 14:57**MOT test number** 345297643294**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2012-09-28 09:33**MOT test number** 597322272270**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-09-27 15:33**MOT test number** 298020871207**Result** ✓ Passed**MOT #3** 2011-09-27 15:33**MOT test number** 148270871288**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #2** 2010-10-04 14:45**MOT test number** 394577170207**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #1** 2009-09-23 13:52**MOT test number** 163116469232**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
26 March 2024

✓

MOT

Expires:
12 September 2024

Tax status	Expired at 26 March 2024
Days left	34 days too late
MOT expiry date	12 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	DK56RHU
Plate since	2019-03-28
Current registration	DK56RHU
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-09-29
Last registration	2023-09-13
Complete history	See info



Registration #1	2006-09-29	29 mi
Registration #2	2009-09-23	23.755 mi
Registration #3	2010-10-04	30.012 mi
Registration #4	2011-09-27	40.342 mi
Registration #5	2012-09-28	48.340 mi
Registration #6	2013-09-04	56.252 mi
Registration #7	2014-09-03	63.939 mi
Registration #8	2015-09-07	71.880 mi
Registration #9	2016-08-23	77.175 mi
Registration #10	2017-09-06	84.162 mi
Registration #11	2018-09-06	91.149 mi
Registration #12	2019-09-06	98.136 mi
Registration #13	2020-09-06	105.123 mi
Registration #14	2021-09-06	112.110 mi
Registration #15	2022-09-06	119.097 mi
Registration #16	2023-09-13	126.084 mi
Registration #17	2024-03-28	133.071 mi
Registration #18	2024-03-28	140.058 mi
Registration #19	2024-03-28	147.045 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1489 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4014833