





report date: 2024-03-29

General information

| Make | MAZDA |
|---------------------|------------------|
| Model | 2 SPORT NAV PLUS |
| Colour | Black |
| Year of manufacture | 2019 |
| Top speed | 117 mph |
| 0 - 60 mph | 9.7 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 89 BHP |
|-------------------------|---------------------|
| Max. torque | 148 Nm at 4.000 rpm |
| Engine capacity | 1.498 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 43.5 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 55.4 mpg |
| CO2 emission | 111 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2022-04-20

Pictures 26

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2024-12-08 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 9 |
| Total items failed | 1 |

| MOT #4 | 2023-11-23 07:48 |
|------------------|------------------|
| MOT test number | 231729968506 |
| Result | √ Passed |
| Next expiry date | 2024-12-08 |

| MOT #3 | 2022-12-09 09:34 |
|--|------------------|
| MOT test number | 366111554774 |
| Result | ✓ Passed |
| Advice Under trays fitted not allowing full inspection of underside components | |

| MOT #2 | 2022-09-21 15:34 |
|---|------------------|
| MOT test number | 344592505212 |
| Result | 🗙 Failed |
| Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) | |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

CarCheck.co.uk page 3/11



BX19XYO

report date: 2024-03-29

MOT #1 2022-03-08 15:31

MOT test number 466203526026

Result ✓ Passed **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Underbody covers fitted not allowing full inspection of underbody components Advice Advice Offside Front Tyre worn close to legal limit/worn on edge very worn inner edge (5.2.3 (e)) **Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 September |
|------------------|-------------------------|
| Days left | 124 |
| MOT expiry date | 8 December 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| * | | |
|---|-----------|---|
| For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively. | | А |
| | | |
| | | |
| *************************************** | | |
| | | |
| ******** | | |
| | | |
| *************************************** | | |
| | More info | > |
| Plate changes | | |
| See in this check if this MAZDA had different number plates. | | |
| Number of plates | | , |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | UK NE | |
| Plate since | | |
| | More info | > |
| | | |

CarCheck.co.uk page 8/11



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2019-03-09 |
| Last registration | 2023-11-23 |
| Complete history | See info |



| Registration #1 | 2019-03-09 | 9 mi |
|-----------------|------------|-----------|
| Registration #2 | 2022-03-08 | 29.725 mi |
| Registration #3 | | 11.777 es |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 71.777 es |

More info >

CarCheck.co.uk page 10/11



Safety ratings

| NCAP rating | *** |
|----------------|-----------------|
| Adult | 86% |
| Children | 78% |
| Pedestrian | 84% |
| Safety systems | 64% |
| Overall rating | 79% |
| Video | see crash video |



Dimensions & weight

| Width | 1983 mm |
|---------------------|---------|
| Height | 1495 mm |
| Length | 4060 mm |
| Wheel base | 2570 mm |
| Max. allowed weight | 1510 kg |

Additional information

| Fuel tank capacity | 44 |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | P5 20567980 |

CarCheck.co.uk page 11/11