



Mercedes-Benz

GRO7AAA


report date: 2024-03-28

General information

Make	MERCEDES
Model	CL 500 500
Colour	Silver
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	5.4 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	383 BHP
Max. torque	530 Nm at 2.800 rpm
Engine capacity	5.462 cc
Cylinders	8
Fuel type	Petrol
Consumption city	15.6 mpg
Consumption extra urban	33.2 mpg
Consumption combined	23.3 mpg
CO2 emission	288 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-09-22
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-26
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	26
Total items failed	8

MOT #17	2024-01-15 12:41
MOT test number	363143006457
Result	✓ Passed
Next expiry date	2025-01-26

MOT #16	2023-01-27 14:33
MOT test number	605743194155
Result	✓ Passed
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Brake disc worn, pitted or scored, but not seriously weakened Both front slight surface corrosion (1.1.14 (a) (ii))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #15** 2023-01-23 12:28**MOT test number** 223834381743**Result** ✗ Failed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both front slight surface corrosion (1.1.14 (a) (ii))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #14** 2021-09-07 08:12**MOT test number** 175050425988**Result** ✓ Passed**MOT #13** 2020-11-04 11:17**MOT test number** 292245754475**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both o/s & n/s front (1.1.14 (a) (ii))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #12** 2020-09-28 11:10**MOT test number** 123268466882**Result** ✗ Failed**Fail** Front Windscreen washer not working (3.5 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both front discs scored (1.1.14 (a) (ii))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #11** 2019-10-10 15:40**MOT test number** 322047492436**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2018-10-04 06:58**MOT test number** 791802676493**Result** ✓ Passed**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #9** 2018-10-03 11:54**MOT test number** 613099527488**Result** ✗ Failed**Fail** Windscreen washer not working (3.5 (a))**Fail** Nearside Windscreen wiper not working (3.4 (a))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #8** 2017-09-13 16:04**MOT test number** 821005636261**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit 2.5mm (4.1.E.1)**Advice** Under trays fitted preventing the full inspection of some components**Advice** Nearside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)

**MOT #7** 2016-08-13 09:14**MOT test number** 757248412808**Result** ✓ Passed**Advice** Under trays fitted obscuring some underside components**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #6** 2015-08-06 14:17**MOT test number** 675648915221**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2015-08-05 13:17**MOT test number** 315807615293**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Fail** Offside Front Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Front Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #4** 2014-08-15 16:17**MOT test number** 358117424287**Result** ✓ Passed**Advice** Offside Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #3** 2013-06-07 10:50**MOT test number** 596328053108**Result** ✓ Passed



MOT #2	2012-02-20 09:27
MOT test number	355791252041
Result	✓ Passed
MOT #1	2010-02-26 12:55
MOT test number	850087250014
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
26 January 2025

Tax status		Valid until 1 March
Days left		306
MOT expiry date		26 January 2025
Full MOT history		See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 GR07AAA
Plate since	2024-03-28
Current registration	 GR07AAA
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-01
Last registration	2024-01-15
Complete history	See info



Registration #1	2007-03-01	10 mi
Registration #2	2010-02-26	18.194 mi
Registration #3	2012-02-20	29.449 mi
Registration #4	2013-06-07	35.888 mi
Registration #5	2014-08-15	39.806 mi
Registration #6	2015-08-05	45.244 mi
Registration #7	2015-08-06	45.249 mi
Registration #8	2016-08-13	49.090 mi
Registration #9	2017-09-13	55.033 mi
Registration #10	2018-10-03	59.729 mi
Registration #11	2019-05-20	65.377 mi
Registration #12	2019-05-20	65.377 mi
Registration #13	2019-05-20	65.377 mi
Registration #14	2019-05-20	65.377 mi
Registration #15	2019-05-20	65.377 mi
Registration #16	2019-05-20	65.377 mi
Registration #17	2019-05-20	65.377 mi
Registration #18	2019-05-20	65.377 mi
Registration #19	2019-05-20	65.377 mi

More info >



Dimensions & weight

Width	1871 mm
Height	1418 mm
Length	5065 mm
Wheel base	2955 mm
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	273961