





General information

Make	VOLKSWAGEN
Model	CC GT TDI BLUEMOTION TECHNOLOGY D
Colour	Grey
Year of manufacture	2013
Top speed	132 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E







Internet history

Entry 1	
Date	2021-02-06
Pictures	10
Listing price	View report









source: autoonline.co.uk



MOT history

MOT expiry date	2024-05-09
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	10
Total items failed	5

MOT #10	2024-04-25 08:33
MOT test number	962615104914
Result	× Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge Wearing on edge (5.2.3 (e))	
Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge Wearing on edge (5.2.3 (e))

МОТ #9	2023-04-27 11:28
MOT test number	272462099461
Result	✓ Passed
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting rear bush (5.3.4 (a) (i))	g in excessive movement
Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice Nearside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting i rear bush (5.3.4 (a) (i))	n excessive movement
Advice Nearside Rear Outer Brake disc worn, pitted or scored, but not seriously	weakened (1.1.14 (a) (ii))





МОТ #8	2022-05-10 13:44
MOT test number	352138839945
Result	✓ Passed
MOT #7	2022-05-04 11:42
MOT test number	457756482480
Result	🗙 Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Electronic stability control warning lamp indicates a fault (7.12 (e))	
Minor Driver's view to the front outside the swept area of the windscreen wipers restricted by an obstruction (3.1 (a) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	

МОТ #6	2021-06-29 14:50
MOT test number	946655695959
Result	✓ Passed

MOT #5	2020-06-24 11:13
MOT test number	842043719576
Result	✓ Passed

MOT #4	2019-06-21 09:13
MOT test number	744583795413
Result	✓ Passed

MOT #3	2018-06-15 14:09
MOT test number	590042913834
Result	✓ Passed





MOT #2	2017-06-23 14:06
MOT test number	538877699930
Result	✓ Passed
MOT #1	2016-06-17 13:53
MOT test number	812497249992
Result	✓ Passed



Tax & MOT check

Tax due: 1 July 2024	√ axed	Expires: 9 May 2024	✓ мот
Tax status			Valid until 1 July
Days left MOT expiry date			63 9 May 2024
Full MOT history			See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FETO
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CUT-S
Date	*
Category	AMPT
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-06-26
Last registration	2024-04-25
Complete history	<u>See info</u>



Registration #1	2013-06-26	19 mi
Registration #2	2016-06-17	17.103 mi
Registration #3	2017-06-23	22.450 mi
Registration #4	2018-06-15	26.743 mi
Registration #5	2019-06-21	30.716 mi
Registration #6	2020-06-24	34.315 mi
Registration #7		
Registration #7 Registration #8		1.77 44
•		01,000 est 01,000 est 01,000 est
Registration #8		0.000 est 0.000 est 0.000 est 0.000 est
Registration #8 Registration #9		0.000 est 0.000 est 0.000 est 0.000 est 0.000 est

More info >





Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight	
Width	2090 mm
Height	1421 mm
Length	4802 mm
Wheel base	2710 mm
Kerb weight	1471 kg
Max. allowed weight	2070 kg
Additional information	
Fuel delivery	Direct Injection
Number of doors	4
Number of axles	2

Engine number

CFFBH89030