





report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Blue
Year of manufacture	2009
Top speed	137 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.198 сс
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/13



Internet history

Fn	trv	1
	ILI Y	-

End y 1	
Date	2021-07-07
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-04-11
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	15
Total items failed	3

MOT #15	2024-04-02 09:25
MOT test number	256542612746
Result	✓ Passed
Next expiry date	2025-04-11
Advice Offside Rear Tyre slightly damaged/cra	cking or perishing (5.2.3 (d) (ii))
Advice Nearside Rear Tyre slightly damaged/cr	racking or perishing (5.2.3 (d) (ii))
Advice Rear Brake pad(s) wearing thin (1.1.13	(a) (ii))

MOT #14		2023-04-03 09:13
MOT test	number	719941316425
Result		✓ Passed
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Rear Suspension arm slight surface corrosion.	

MOT #13	2022-04-08 08:07
MOT test number	766929001682
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT #12 2021-04-12 11:25

MOT test number 751794316410

Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #11 2020-04-06 09:45

MOT test number 845816290223

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10 2019-04-05 10:13

MOT test number 938618343126

Result \rightarrow Passed

Advice Front and rear brake pads worn. front brake discs worn on inner faces.

MOT #9 2018-03-22 11:57

MOT test number 957441755588

Result ✓ Passed

MOT #8 2017-04-11 10:32

MOT test number 678438957351

Result ✓ Passed

MOT #7 2017-04-10 15:23

MOT test number 785286524221

Result X Failed

Fail Shock absorber has a serious fluid leak both rears (2.7.3)

CarCheck.co.uk page 4/13



Result

YK09YYL report date: 2024-03-28

Passed

MOT #6 2016-02-25 12:54

MOT test number 342709774289

Result ✓ Passed

Advice Engine covers fitted obscuring some components in the engine bay

Advice Nearside Rear wheel bearing has slight play (2.6.2)

Advice Under-trays fitted obscuring some underside components

MOT #5 2015-03-10 14:33

MOT test number 819879065094

Result \sqrt{Passed}

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

MOT #4 2014-03-05 12:26

MOT test number 729844664084

Advice Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

Notice Under-trays fitted obscuring some underside components

MOT #3 2013-03-06 08:54

MOT test number 146665163024

Result ✓ Passed

MOT #2 2013-03-05 10:12

MOT test number 188274563402

Result X Failed

Fail Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

Fail Offside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

CarCheck.co.uk page 5/13



MOT #1 2012-03-09 11:32

MOT test number 538229862081

Result ✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

Owner mistory	
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	OK SIN
Plate since	
Current registration	UK ZIS
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-03-11
Last registration	2024-04-02
Complete history	See info



Registration #1	2009-03-11	17 mi
Registration #2	2012-03-09	22.004 mi
Registration #3	2013-03-05	26.025 mi
Registration #4	2013-03-06	26.036 mi
Registration #5	2014-03-05	29.571 mi
Registration #6	2015-03-10	33.568 mi
Registration #7	2016-02-25	36.120 mi
Registration #8	2017-04-10	39.760 mi
Registration #9	2017-04-11	39.760 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		D.177 es

More info >

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

var tot	2002
Width	2003 mm
Height	1395 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	61 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	090409201123BG

CarCheck.co.uk page 13/13