




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO GTI
Colour	Black
Year of manufacture	2016
Top speed	147 mph
0 - 100 km/h	6.7 seconds
0 - 60 mph	6.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 kW / 192 HP / 189 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-10-14
Pictures	17
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-07-28
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	9
Total items failed	1

## MOT #6 2023-07-14 14:52

MOT test number 476204295731

Result ✓ Passed

Next expiry date 2024-07-28

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Parking brake lever defective but can be satisfactorily operated reserve travel (1.1.6 (d))

## MOT #5 2022-07-07 15:05

MOT test number 335792948343

Result ✓ Passed

**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**Advice** Tyre worn close to legal limit/worn on edge all four tyres under 3mm front wearing more inner edge (5.2.3 (e))

## MOT #4 2022-07-07 15:05

MOT test number 863539305628

Result ✗ Failed

**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**Advice** Tyre worn close to legal limit/worn on edge all four tyres under 3mm front wearing more inner edge (5.2.3 (e))

**Pass with rectification** Parking brake lever has excessive movement indicating incorrect adjustment adjusted cable (1.1.6 (c))

**MOT #3** 2021-07-21 07:53**MOT test number** 730150566223**Result** ✓ Passed**MOT #2** 2020-07-29 09:44**MOT test number** 862504726217**Result** ✓ Passed

**Advice** Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))

**Advice** Offside Front Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #1** 2019-07-31 08:05**MOT test number** 620328678367**Result** ✓ Passed

**Advice** Engine cover and undertrays fitted, restricting view of some testable items.



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
28 July 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	28 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>BD16BWN</b>
Plate since	2019-03-29
Current registration	<b>BD16BWN</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-06-30
Last registration	2023-07-14
Complete history	<a href="#">See info</a>



Registration #1	2016-06-30	14 mi
Registration #2	2019-07-31	25.588 mi
Registration #3	2020-07-29	38.958 mi
Registration #4	2021-07-21	47.287 mi
Registration #5	2022-06-29	55.277 mi
Registration #6	2022-06-29	55.277 mi
Registration #7	2022-06-29	55.277 mi
Registration #8	2023-07-14	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1901 mm
Height	1462 mm
Length	3972 mm
Wheel base	2470 mm
Kerb weight	1172 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3

**Number of axles**

2

**Engine number**

DAJA014876