





report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT 111
Colour	Silver
Year of manufacture	2006
Top speed	124 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP	
Max. torque	148 Nm at 3.750 rpm	
Engine capacity	1.598 сс	
Cylinders	4	
Fuel type	Petrol	
Consumption city	30.1 mpg	
Consumption extra urban	49.6 mpg	
Consumption combined	40.4 mpg	
CO2 emission	166 g/km	
CO2 label	Н	



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 1

Date 2021-02-04

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

MOT history

MOT expiry date	2022-05-24
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	22
Total items failed	12

MOT #19	2021-05-25 14:41
MOT test number	908018475042
Result	✓ Passed
Next expiry date	2022-05-24

MO1 #10	2021-05-25 15:15
MOT test number	313527384765
Result	X Failed
Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Fail Nearside Position lamp not working (4.2.1 (a) (ii))	

MOT #17	2020-04-16 09:45
MOT test number	839314746731
Result	✓ Passed

MOT #16	2020-04-16 09:45
MOT test number	872801681162
Result	▼ Failed
Pass with rectification	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT test number

Result

Advice Front Play in steering rack inner joint(s) offside and nearside

Advice Front Brake pad(s) wearing thin offside and nearside (1.1.13 (a) (ii))

Advice Rear Tyre worn close to legal limit/worn on edge offside and nearside (5.2.3 (e))

MOT #14

MOT test number

Result

Advice Hand brake just passed need further attenstion

Advice Nearside Front coil spring corroded (2.4.C.1b)

MOT test number

Result

Advice

N/s o/s rear tyres start to crack

Advice

Oil leak

Advice

Engine cover fitted and under tray fitted

MOT #12

MOT test number

861771201131

Result

Advice Engine cover fitted and under tray fitted

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #11		2015-04-24 09:40
MOT test	number	498924915191
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	

MOT #10		2014-04-04 16:57
MOT test	number	337144394057
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Advice	Offside Front Track rod end ball joint has slight play (2.2.B.1f)	
Notice	Under-trays fitted obscuring some underside components	
Advice	Nearside Front Track rod end ball joint has slight play (2.2.B.1f)	

MOT #9	2013-04-08 13:28
MOT test number	655148793095
Result	✓ Passed
MOT #8	2012-11-14 09:29
MOT test number	709619112305
Result	✓ Passed
MOT #7	2012-11-13 15:52

MOT #7	2012-11-13 15:52
MOT test number	407938912317
Result	X Failed
Fail Brakes imbalanced across an axle (3.7.B.5b)	

CarCheck.co.uk page 5/14



MOT #3

MX56HXG

report date: 2024-03-28

2011-09-27 16:35



MOT #5	2012-09-25 11:45
MOT test number	855979762202
Result	🗙 Failed
Notice Slight play o/s steering arm	
Fail Nearside Rear Direction indicator incorrect colour (1.4.A.2f)	
Fail Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)	
Fail Offside Rear rear brake binding (3.7.B.1)	
Fail Nearside Front position lamp(s) not working (1.1.A.3b)	
Notice Slight play n/s steering arm	
Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f)	
Fail Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)	
Fail Offside Rear rear brake juddering severely (3.7.A.5b)	

MOT #4	2011-09-28 10:13
MOT test number	789821171240
Result	✓ Passed

MOT t	est number	199340271251
Result		X Failed
Fail	Nearside Outer Front constant velocity joint gaiter insecurely mounted to its housing	(2.5.C.1a)

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #2		2010-09-28 12:05
MOT test	number	851011370260
Result		✓ Passed
MOT #1		2009-09-24 15:56
MOT test	number	310977869260
Result		✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Notice	Nearside rear tyre slight sidewall deterioration	
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 7/14



MX56HXG report date: 2024-03-28

Tax & MOT check



MOT
Expired:
24 May 2022

Tax expired: 18 October 2019

Tax status

Days left

MOT expiry date

Full MOT history

Expired at 18 October 2019

1654 days too late

24 May 2022

See MOT history

Tax calculation

Vahiala alasa	40
Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
HARMAN CO. C.	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-09-25
Last registration	2021-05-25
Complete history	See info



Registration #1	2006-09-25	26 mi
Registration #2	2009-09-24	17.342 mi
Registration #3	2010-09-28	21.405 mi
Registration #4	2011-09-27	26.498 mi
Registration #5	2011-09-28	26.498 mi
Registration #6	2012-09-25	31.542 mi
Registration #7	2012-09-28	31.545 mi
Registration #8	2012-11-13	32.073 mi
Registration #9	2012-11-14	32.073 mi
Registration #10	2013-04-08	32.066 mi
Registration #11	2014-04-04	39.472 mi
Registration #12		77.777 46
Registration #13		77.777 66
Registration #14		77.777 es
Registration #15		77.777 66
Registration #16		77,777 44
Registration #17		77.777 66
Registration #18		77.777 es
Registration #19		11.117 es
Registration #19 Registration #20		7.77 44

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1698 mm
Height	1366 mm
Length	4028 mm
Wheel base	2522 mm
Kerb weight	1320 kg
Max. allowed weight	1775 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 14/1