



report date: 2024-03-29

## General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Blue
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B






Internet history

Entry 2


Date	2021-12-29
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-12-19
Pictures	25
Listing price	<a href="#">View report</a>



source: [yesauto.com](#)

**MOT history**

<b>MOT expiry date</b>	2025-01-13
<b>MOT pass rate</b>	86 %
<b>MOT passed</b>	12
<b>Failed MOT tests</b>	2
<b>Total advice items</b>	10
<b>Total items failed</b>	4

<b>MOT #14</b>	2024-01-08 09:45
<b>MOT test number</b>	590366628586
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2025-01-13
<b>Advice</b>	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

<b>MOT #13</b>	2023-01-10 08:56
<b>MOT test number</b>	569189554204
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

<b>MOT #12</b>	2022-01-14 13:38
<b>MOT test number</b>	442499740920
<b>Result</b>	✓ Passed

<b>MOT #11</b>	2021-03-19 09:35
<b>MOT test number</b>	387301824596
<b>Result</b>	✓ Passed

<b>MOT #10</b>	2020-03-25 08:07
<b>MOT test number</b>	602825001572
<b>Result</b>	✓ Passed

**MOT #9** 2019-03-11 17:05**MOT test number** 608637392675**Result** ✓ Passed**MOT #8** 2019-03-11 17:05**MOT test number** 570778100856**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Offside Rear Upper Position lamp not working (4.2.1 (a))**MOT #7** 2018-03-16 11:13**MOT test number** 468685655302**Result** ✓ Passed**MOT #6** 2017-03-30 11:33**MOT test number** 929125846842**Result** ✓ Passed**MOT #5** 2016-03-10 11:33**MOT test number** 847638700405**Result** ✓ Passed**MOT #4** 2015-03-09 14:43**MOT test number** 116148765005**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



MOT #3	2015-03-09 14:43
MOT test number	376298465024
Result	✗ Failed
Notice	Under-trays fitted obscuring some underside components
Pass with rectification	Offside Rear Direction indicator incorrect colour (1.4.A.2f)
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Engine covers fitted obscuring some components in the engine bay
Pass with rectification	Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

MOT #2	2014-03-31 11:51
MOT test number	687390594081
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #1	2013-08-13 12:06
MOT test number	528135723299
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 January 2025

✓  
**MOT**

**Expires:**  
13 January 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	13 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-10-25
Last registration	2024-01-08
Complete history	<a href="#">See info</a>



Registration #1	2010-10-25	7 mi
Registration #2	2013-08-13	30.552 mi
Registration #3	2014-03-31	33.806 mi
Registration #4	2015-03-09	41.341 mi
Registration #5	2016-03-10	47.343 mi
Registration #6	2017-03-30	51.841 mi
Registration #7	2018-03-16	56.530 mi
Registration #8	2019-03-11	60.892 mi
Registration #9	2020-03-20	65.254 mi
Registration #10	2021-03-20	69.616 mi
Registration #11	2022-03-20	73.978 mi
Registration #12	2023-03-20	78.340 mi
Registration #13	2024-01-08	82.702 mi
Registration #14		
Registration #15		
Registration #16		

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1260602