





report date: 2024-03-28

### General information

| Make                | PEUGEOT        |
|---------------------|----------------|
| Model               | 107 URBAN      |
| Colour              | Yellow         |
| Year of manufacture | 2007           |
| Top speed           | 100 mph        |
| 0 - 60 mph          | 14.2 seconds   |
| Gearbox             | 5 speed Manual |

### Engine & fuel consumption

| Power                   | 67 BHP             |
|-------------------------|--------------------|
| Max. torque             | 93 Nm at 3.600 rpm |
| Engine capacity         | 998 сс             |
| Cylinders               | 3                  |
| Fuel type               | Petrol             |
| Consumption city        | 51.4 mpg           |
| Consumption extra urban | 68.9 mpg           |
| Consumption combined    | 61.4 mpg           |
| CO2 emission            | 109 g/km           |
| CO2 label               | В                  |



CarCheck.co.uk page 1/13



### Internet history

#### Entry 1

Date 2021-02-03

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

| MOT expiry date    | 2024-01-02 |
|--------------------|------------|
| MOT pass rate      | 74 %       |
| MOT passed         | 14         |
| Failed MOT tests   | 5          |
| Total advice items | 27         |
| Total items failed | 10         |

| MOT #19   | 2024-01-02 17:49       |
|---|------------------------|
| MOT test number   | 538408606754           |
| Result  | <b>×</b> Failed        |
| Fail Nearside Rear Suspension component mounting prescribed area excessively reducing structural strength trailing arm mount (5.3.6 (a) (i))          | corroded significantly |
| Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakene   | ed (1.1.14 (a) (ii))   |
| Fail Offside Rear Service brake excessively binding (1.2.1 (f))   |                        |
| Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weaker   | ned (1.1.14 (a) (ii))  |
| <b>Fail</b> Offside Rear Suspension component mounting prescribed area excessively correducing structural strength trailing arm mount (5.3.6 (a) (i)) | orroded significantly  |
| Advice Parking brake lever has little reserve travel  |                        |

| MOT #18   | 2023-01-03 10:29          |
|---|---------------------------|
| MOT test number   | 282224920777              |
| Result  | ✓ Passed                  |
| Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))   |                           |
| Advice Suspension component mounting prescribed area is corroded but not corrosion detected around beam axle mounting points both sides (5.3.6 (a) (i)) | nsidered excessive slight |
| Advice Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))  |                           |

CarCheck.co.uk page 3/13



WJ07AUU

report date: 2024-03-28

**MOT #17** 2022-10-29 08:29

**MOT test number** 628767955874

**Result** ✓ Passed

Advice Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

Advice Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))

MOT #16 2021-11-23 10:23

**MOT test number** 724954494936

Result 

Passed

Advice Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))

**Advice** O/s/f tyre starting to wear low on the inner edge

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both front lower arm rear bushes (5.3.4 (a) (i))

**MOT #15** 2021-11-19 12:05

MOT test number 260768571998

**Result** X Failed

**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both front lower arm rear bushes (5.3.4 (a) (i))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

**Advice** O/s/f tyre starting to wear low on the inner edge

**Advice** Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))

CarCheck.co.uk page 4/13



WJ07AUU

report date: 2024-03-28

MOT test number

Result

Minor

Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #13 2020-11-18 16:51 828409567881 **MOT** test number Result × Failed Fail Nearside Rear Seat belt missing (7.1.2 (a)) Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i)) Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c)) **Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Fail Offside Rear Seat belt missing (7.1.2 (a))

| MOT #12    |   | 2019-04-23 12:44        |
|------------|---|-------------------------|
| MOT test i | number  | 664521400684            |
| Result     |   | <b>✓</b> Passed         |
| Advice     | Rear exhaust rusty  |                         |
| Advice     | Surface rust to nearside and offside rear inner sills                       |                         |
| Advice     | Anti-roll bar pin or bush worn but not resulting in excessive movement Both | n front (5.3.4 (a) (i)) |

CarCheck.co.uk page 5/13



Result

WJO7AUU report date: 2024-03-28

× Failed

MOT #11

MOT test number

461483032641

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside rear wheel baring slight rough

MOT #10

MOT test number

Result

Advice Brake hose has slight corrosion to ferrules (3.6.B.4e)

 MOT #9
 2016-04-26 08:02

 MOT test number
 428739789283

 Result
 ✓ Passed

MOT #8 2015-05-01 13:05

MOT test number 617781025104

Result ✓ Passed

MOT #7 2015-04-20 11:00

**MOT test number** 469400215128

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

 MOT #6
 2014-03-18 08:43

 MOT test number
 989257674025

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



MOT #5 2013-03-16 10:11 **MOT test number** 406725473093 Result ✓ Passed MOT #4 2012-03-05 08:47 **MOT** test number 408065462078 Result ✓ Passed MOT #3 2011-02-16 12:07 **MOT test number** 219877041058 Result ✓ Passed MOT #2 2010-03-05 09:08 171924460422 **MOT test number** Result ✓ Passed **MOT #1** 2010-03-03 15:09 **MOT test number** 110632860421 Result × Failed Fail Indicator switch faulty (1.4.A.1)

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

| Damage 1 |  |
|----------|--|
| Date     |  |
| Category |  |
| Туре     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Type     |  |



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



### Owner history

| For how long did the current and previous owner(s) have this PEUGEOT? How many own have? Check it in the premium report and see all owner registrations. Download the full |             |
|--|-------------|
|  |             |
| manus .  |             |
| ***************************************  |             |
| ***************************************  |             |
|  |             |
| manus .  |             |
| ***************************************  |             |
| ***************************************  |             |
|  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this PEUGEOT had different number plates.   |             |
|  |             |
| Number of plates   | ,           |
|  |             |
| Current registration   | NK SIE      |
| Plate since  |             |
| Current registration   | SIE UK      |
| Fiate since  |             |
|  |             |
|  | More info > |

CarCheck.co.uk page 10/13



#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Courts at info    |  |

**Contact info** 


More info >

CarCheck.co.uk page 11/13



Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 21         |
| First mileage registration | 2007-03-05 |
| Last registration          | 2024-01-02 |
| Complete history           | See info   |



| Registration #1                   | 2007-03-05 | 24 mi       |
|-----------------------------------|------------|-------------|
| Registration #2                   | 2010-03-03 | 2.342 mi    |
| Registration #3                   | 2010-03-05 | 2.342 mi    |
| Registration #4                   | 2011-02-16 | 2.587 mi    |
| Registration #5                   | 2012-03-05 | 9.945 mi    |
| Registration #6                   | 2013-03-16 | 32.245 mi   |
| Registration #7                   | 2014-03-18 | 50.671 mi   |
| Registration #8                   | 2015-04-20 | 54.886 mi   |
| Registration #9                   | 2015-05-01 | 54.886 mi   |
| Registration #10                  | 2016-04-26 | 57.628 mi   |
| Registration #11                  | 2017-04-27 | 60.606 mi   |
| Registration #12                  |            | 77.777 es   |
| Registration #13                  |            | 77.777 66   |
| Registration #14                  |            | 77.777 es   |
| Registration #15                  |            | 77.777 66   |
| Registration #16                  |            | 77,777 44   |
| Registration #17                  |            | 77.777 66   |
| Registration #18                  |            | 111.7177 mg |
|                                   |            |             |
| Registration #19                  |            | 71.777 es   |
| Registration #19 Registration #20 |            | 11.777 ea   |

More info >

CarCheck.co.uk page 12/13



### Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

## Safety ratings

| NCAP rating | ****            |
|-------------|-----------------|
| Video       | see crash video |



### Dimensions & weight

| Width               | 1630 mm |
|---------------------|---------|
| Height              | 1465 mm |
| Length              | 3430 mm |
| Wheel base          | 2340 mm |
| Kerb weight         | 825 kg  |
| Max. allowed weight | 1190 kg |

# Additional information

| Fuel tank capacity                | 35 I                  |
|-----------------------------------|-----------------------|
| Fuel delivery                     | Multi-Point Injection |
| Number of doors                   | 5                     |
| Number of seats<br>CarCheck.co.uk | 4 page 13/1           |