



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO VVT-I TR
Colour	Silver
Year of manufacture	2007
Top speed	121 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	44.1 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	I






Internet history

Entry 1

Date	2022-02-12
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-02-10
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	39
Total items failed	8

MOT #19 2022-02-03 14:26

MOT test number 727324035292

Result ✓ Passed

Next expiry date 2023-02-10

- Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn both (5.1.2 (b) (i))
- Minor** Offside Rear Tyre obviously under inflated (5.2.3 (I))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Minor** Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Driver's door hinge deteriorated but the door can still be readily opened and closed (6.2.3 (c) (i))

MOT #18 2021-02-11 10:16

MOT test number 321257564995

Result ✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #17 2020-02-11 13:09

MOT test number 282132333898

Result ✓ Passed

- Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn both side (5.1.2 (b) (i))

**MOT #16** 2020-02-11 13:09**MOT test number** 829483540052**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn both side (5.1.2 (b) (i))**Pass with rectification** Front Headlamp not working on dipped beam both side (4.1.1 (a) (ii))**MOT #15** 2019-08-30 13:17**MOT test number** 143867950186**Result** ✓ Passed**MOT #14** 2019-08-30 13:17**MOT test number** 481103756340**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #13** 2019-06-17 14:46**MOT test number** 300462332351**Result** ✓ Passed**MOT #12** 2018-06-05 08:26**MOT test number** 486528180206**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11** 2017-06-17 11:13**MOT test number** 812225394552**Result** ✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Front Brake pad(s) modified but not seriously weakened (3.5.1n)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #10 2016-07-05 12:14**MOT test number** 948582440820**Result** ✓ Passed**MOT #9** 2016-06-25 09:50**MOT test number** 821830007818**Result** ✗ Failed

- Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
- Advice** Dipstick tube broken
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Front Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2015-06-24 12:04**MOT test number** 788605775113**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components



MOT #7	2014-06-27 09:41
MOT test number	608088074191
Result	✓ Passed

MOT #6	2013-06-26 15:23
MOT test number	435607173154
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Nearside rear tyre slight twist in tread
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)
Notice	Child seat fitted not allowing full inspection of adult belt

MOT #5	2013-06-26 09:23
MOT test number	935277273133
Result	✗ Failed
Fail	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Notice	Child seat fitted not allowing full inspection of adult belt
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Front Steering system has a road wheel fouling a part of the vehicle (2.2.D.2a)
Notice	Nearside rear tyre slight twist in tread
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2012-06-29 15:44**MOT test number** 206161982173**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-05-25 12:26**MOT test number** 308885441157**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-05-25 12:26**MOT test number** 775285441193**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2010-06-21 16:26**MOT test number** 993422470189**Result** ✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-05-31
Last registration	2022-02-03
Complete history	See info



Registration #1	2007-05-31	15 mi
Registration #2	2010-06-21	14.328 mi
Registration #3	2011-05-25	22.207 mi
Registration #4	2012-06-29	36.080 mi
Registration #5	2013-06-26	43.137 mi
Registration #6	2013-06-26	43.137 mi
Registration #7	2014-06-27	52.322 mi
Registration #8	2015-06-24	60.831 mi
Registration #9	2016-06-25	72.187 mi
Registration #10	2016-07-05	72.187 mi
Registration #11	2016-06-25	72.187 mi
Registration #12	2016-06-25	72.187 mi
Registration #13	2016-06-25	72.187 mi
Registration #14	2016-06-25	72.187 mi
Registration #15	2016-06-25	72.187 mi
Registration #16	2016-06-25	72.187 mi
Registration #17	2016-06-25	72.187 mi
Registration #18	2016-06-25	72.187 mi
Registration #19	2016-06-25	72.187 mi
Registration #20	2016-06-25	72.187 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Engine number

1ZZU896971