





report date: 2024-03-28

General information

Make	FIAT
Model	PANDA POP
Colour	White
Year of manufacture	2013
Top speed	102 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-09

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-07-19
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	8
Total items failed	1

MOT #9	2023-07-10 10:06
MOT test number	721913949838
Result	✓ Passed
Next expiry date	2024-07-19
Advice Nearside Play in steering rack inner joint(s)	

MOT #8	2022-07-07 14:04
MOT test number	634254853802
Result	✓ Passed

Result	✓ Passeu
MOT #7	2021-07-20 11:05
MOT test number	257071725345
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal I (5.2.3 (e))	imit/worn on edge Tyre beginning to wear on outer edge.

MOT #6	2020-12-11 16:54
MOT test number	595023782018
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #5 2020-12-11 15:28

MOT test number 916010063220

Result X Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2019-10-29 15:01

MOT test number 465677160026

Result \(\sqrt{Passed} \)

MOT #3 2018-11-08 12:44

MOT test number 964640293586

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2017-12-15 16:31

MOT test number 360509074976

Result \(\sqrt{Passed} \)

Advice Nearside Front Tyre worn close to the legal limit on limit (4.1.E.1)

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2016-12-23 11:02

MOT test number 505912359544

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	19 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11




report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

,	
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>I</u>	

THE REAL PROPERTY OF THE PERTY	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	AK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-12-17
Last registration	2023-07-10
Complete history	See info



Registration #1	2013-12-17	28 mi
Registration #2	2016-12-23	38.637 mi
Registration #3	2017-12-15	50.599 mi
Registration #4	2018-11-08	64.280 mi
Registration #5	2019-10-29	72.041 mi
Registration #6	2020-12-11	81.233 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1882 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	37 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles CarCheck.co.uk	2 page 11/11

Engine number

0341597