



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Grey
Year of manufacture	-
Top speed	129 mph
Gearbox	4 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-29
Pictures	43
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT #17	2022-10-10 13:57
MOT test number	586091646298
Result	✓ Passed
Next expiry date	2023-10-10
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16	2022-10-10 08:39
MOT test number	826909743888
Result	✗ Failed
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Minor	Offside Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #15	2021-10-11 09:45
MOT test number	128769972861
Result	✓ Passed

MOT #14	2021-10-08 14:45
MOT test number	252921437012
Result	✗ Failed
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**MOT #13**

2021-03-23 10:03

**MOT test number**

114358104993

**Result**

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front headlight intensity slightly reduced
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #12**

2020-03-09 17:30

**MOT test number**

778963597351

**Result**

✓ Passed

- Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11**

2020-03-09 09:30

**MOT test number**

300841830766

**Result****✗ Failed****Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10**

2019-04-08 16:24

**MOT test number**

289793415226

**Result****✓ Passed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9**

2019-04-08 10:09

**MOT test number**

853309054926

**Result****✗ Failed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge uneven wear inner edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing tread cracking (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #8** 2018-04-05 12:42**MOT test number** 503713837627**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit tyre also heavily cracked (4.1.E.1)**Advice** Parking brake efficiency only just met requirements**MOT #7** 2017-04-05 09:17**MOT test number** 929149131405**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-04-06 15:08**MOT test number** 764140254560**Result** ✓ Passed**Advice** Transmission oil leak**Advice** Offside Rear Tyre perishing**MOT #5** 2016-04-05 09:55**MOT test number** 151171551324**Result** ✗ Failed**Advice** Transmission oil leak**Fail** Rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Offside Rear Tyre perishing

**MOT #4** 2015-03-30 12:46**MOT test number** 669459285059**Result** ✓ Passed**MOT #3** 2014-04-08 11:47**MOT test number** 685928594075**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Offside rear tyre perished / cracking**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2013-04-09 10:27**MOT test number** 166169993082**Result** ✓ Passed**MOT #1** 2012-03-28 09:09**MOT test number** 346308882097**Result** ✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-31
Last registration	2022-10-10
Complete history	<a href="#">See info</a>



Registration #1	2009-03-31	24 mi
Registration #2	2012-03-28	17.314 mi
Registration #3	2013-04-09	23.458 mi
Registration #4	2014-04-08	30.373 mi
Registration #5	2015-03-30	36.718 mi
Registration #6	2016-04-05	44.261 mi
Registration #7	2016-04-06	44.289 mi
Registration #8	2017-04-05	50.956 mi
Registration #9	2018-04-05	56.916 mi
Registration #10	2019-04-08	62.093 mi
Registration #11	2019-05-29	65.377 mi
Registration #12	2019-05-29	65.377 mi
Registration #13	2019-05-29	65.377 mi
Registration #14	2019-05-29	65.377 mi
Registration #15	2019-05-29	65.377 mi
Registration #16	2019-05-29	65.377 mi
Registration #17	2019-05-29	65.377 mi
Registration #18	2019-05-29	65.377 mi
Registration #19	2019-05-29	65.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1342 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC8231151