





# General information

Make	FIAT
Model	500L MULTIJET TREKKING DUALOGIC
Colour	Turquoise
Year of manufacture	2015
Top speed	101 mph
Gearbox	5 speed Semi-Automatic

# Engine & fuel consumption

Power	94 BHP	0 < 101 A
Max. torque	200 Nm at 1.500 rpm	101 - 120 B
Engine capacity	1.248 cc	121 - 140 E
Cylinders	4	141 - 165 <sup>F</sup> <sub>G</sub>
Fuel type	Diesel	166 - 185 H
Consumption city	62.8 mpg	186 - 225 J
Consumption extra urban	76.4 mpg	225+ L M
Consumption combined	70.6 mpg	
CO2 emission	106 g/km	
CO2 label	В	





## Internet history

Entry	3
Date	

Pictures

2021-10-13

4

Listing price

View report



source: cargurus.co.uk

Entry 2	
Date	2021-10-12
Pictures	4
Listing price	View report









source: autotrader.co.uk

#### Entry 1

Entry 1	
Date	2021-01-29
Pictures	1
Listing price	View report



source: autoonline.co.uk



# MOT history

MOT expiry date	2024-11-24
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	7
Total items failed	9

MOT #8	2023-11-13 15:46
MOT test number	963414469422
Result	✓ Passed
Next expiry date	2024-11-24

MOT #7	2022-11-24 14:48
MOT test number	204595087819
Result	🗸 Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #6	2021-11-25 13:34
MOT test number	587785583602
Result	✓ Passed



Μ	We	55	U	W	F
	repo	rt dat	: <b>e:</b> 2	024-0	3-28

MOT #5	2021-11-24 12:20
MOT test number	527584666726
Result	🗙 Failed
<b>Fail</b> Nearside Rear Tyre has a lump, caused by separation or partial failure of its (5.2.3 (d) (ii))	structure out of shape
<b>Fail</b> Offside Steering rack has excessive free play detected at the steering whee rack end (2.3 (a) (i))	l (steering rack fitted)
Fail Rear Brake disc in such a condition that it is seriously weakened worn and p	itted (1.1.14 (a) (ii))
Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5)	.2.3 (h))
<b>Fail</b> Offside Rear Tyre has a lump, caused by separation or partial failure of its s (5.2.3 (d) (ii))	tructure out of shape

MOT #4	2020-10-19 13:25
MOT test number	487465597663
Result	✓ Passed

MOT #3		2019-09-25 09:08
MOT test	number	366230252443
Result		✓ Passed
Advice	Nearside Rear Brake cable damaged but not to excess Park cable. (1.1.15 (a))	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Vehicles internal headlight adjuster altered to recheck lights	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #2	2018-10-24 13:02
MOT test number	484663912166
Result	✓ Passed





MOT #1	L 2018-10-23 13:31
MOT te	<b>st number</b> 508068901353
Result	× Failed
Fail	Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



mw65UwF report date: 2024-03-28

# Tax & MOT check

✓ Taxed Tax due:	✓ MOT Expires:
1 November 2024	24 November 2024
Tax status	Valid until 1 November
Days left	187
MOT expiry date	24 November 2024
Full MOT history	See MOT history
Tax calculation	

# Vehicle class49BandBSingle payment (12 months)£ 20,00,-Single six month paymentNot applicableTotal payable by 12 monthly instalments£ 21,00,-





## Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Duniuge 2	E E E E
Date	J.
Category	amer
Туре	

#### Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





## Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
********	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





## Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-12-16
Last registration	2023-11-13
Complete history	<u>See info</u>



Registration #1	2015-12-16	18 mi
Registration #2	2018-10-23	23.334 mi
Registration #3	2018-10-24	23.334 mi
Registration #4	2019-09-25	29.609 mi
Registration #5	2020-10-19	34.049 mi
Registration #6		11.117 esi
Registration #7		11.117 mi
Registration #8		11.777 esi
Registration #9		11.777 esi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 esi





## Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
\$0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight	
Width	1800 mm
Height	1679 mm
Length	4270 mm
Wheel base	2612 mm
Kerb weight	1315 kg
Max. allowed weight	1855 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	5898911