



HYUNDAI



AFIIRVM


report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI PREMIUM
Colour	Silver
Year of manufacture	2011
Top speed	108 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 4

Date	2022-11-14
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 3

Date	2022-06-17
Pictures	18
Listing price	View report



source: [cargurus.co.uk](#)

Entry 2


Date	2021-08-22
Pictures	19
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-05-23
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-09-08
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	8
Total items failed	11

MOT #13	2022-09-09 08:16
MOT test number	445924131520
Result	✓ Passed
Next expiry date	2023-09-08

MOT #12	2021-11-05 13:15
MOT test number	164716538647
Result	✓ Passed

MOT #11	2021-11-04 10:00
MOT test number	428130467539

Result	✗ Failed
--------	----------

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Service brake binding but not excessively (1.2.1 (f))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))



MOT #10	2021-01-30 09:15
MOT test number	849040911479
Result	✓ Passed
Advice	Clutch pedal anti slip missing

MOT #9	2020-01-24 14:56
MOT test number	510167428996
Result	✓ Passed
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #8	2019-02-18 13:39
MOT test number	347483709573
Result	✓ Passed
Advice	Nearside Rear Nail in tyre

MOT #7	2019-02-15 10:13
MOT test number	994833931504
Result	✗ Failed
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Offside Rear Parking brake inoperative on one side (1.4.1 (a))
Fail	Nearside Front Position lamp not working (4.2.1 (a))
Fail	Central Rear Trailer electrical socket (13 pin) not operating the trailer lamps as intended (4.10 (c) (i))
Advice	Nearside Rear Nail in tyre
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Brake pedal has insufficient reserve travel (1.1.2 (a))
Fail	Offside Front Position lamp not working (4.2.1 (a))

**MOT #6** 2018-02-15 09:02**MOT test number** 673086016782**Result** ✓ Passed**MOT #5** 2018-02-15 09:02**MOT test number** 460735055605**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2017-05-09 14:39**MOT test number** 370173723348**Result** ✓ Passed**MOT #3** 2016-05-18 10:24**MOT test number** 883728157795**Result** ✓ Passed**MOT #2** 2015-05-29 09:24**MOT test number** 649229245155**Result** ✓ Passed**MOT #1** 2014-06-06 17:22**MOT test number** 939447154156**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
30 September 2023

X

MOT

Expired:
8 September 2023

Tax status	Expired at 30 September
Days left	212 days too late
MOT expiry date	8 September 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2023-03-28
Current registration	XXXXXX
Plate since	2023-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-03-31
Last registration	2022-09-09
Complete history	See info



Registration #1	2011-03-31	11 mi
Registration #2	2014-06-06	24.104 mi
Registration #3	2015-05-29	35.611 mi
Registration #4	2016-05-18	46.263 mi
Registration #5	2017-05-09	58.756 mi
Registration #6	2018-02-15	69.145 mi
Registration #7	2018-02-15	69.145 mi
Registration #8	2019-02-15	79.890 mi
Registration #9	2019-02-18	79.891 mi
Registration #10	2019-05-29	85.377 mi
Registration #11	2019-05-29	85.377 mi
Registration #12	2019-05-29	85.377 mi
Registration #13	2019-05-29	85.377 mi
Registration #14	2019-05-29	85.377 mi
Registration #15	2019-05-29	85.377 mi
Registration #16	2019-05-29	85.377 mi
Registration #17	2019-05-29	85.377 mi
Registration #18	2019-05-29	85.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1670 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDBZ014741