




report date: 2024-03-28

General information

Make	FORD
Model	FOCUS C-MAX GHIA TDCI
Colour	Blue
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg





Internet history

Entry 1

Date	2021-08-27
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #22	2021-02-25 11:49
MOT test number	577501111127
Result	✓ Passed
Next expiry date	2022-03-08
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #21	2020-02-19 09:56
MOT test number	884074638565
Result	✓ Passed
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #20	2019-02-13 08:59
MOT test number	340578135714
Result	✓ Passed
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))
Advice	Nearside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both slightly pitted (1.1.14 (a) (ii))



MOT #19 2019-02-11 11:24

MOT test number 879758119603

Result ✗ Failed

- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both slightly pitted (1.1.14 (a) (ii))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Rear Exhaust mounting defective tailpipe (6.1.2 (a))
- Advice** Nearside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #18 2018-02-21 12:02

MOT test number 340584264624

Result ✓ Passed



MOT #17 2018-02-21 12:02

MOT test number 166461241119

Result ✗ Failed

Pass with rectification Headlamp aim beam image obviously incorrect both (1.8.A.1b)

MOT #16 2017-02-28 16:13

MOT test number 444253148366

Result ✓ Passed

- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside rear brake binding slightly
- Advice** Rear exhaust hanger broken/corroded
- Advice** Front Headlamp deteriorated but light output not reduced Both (1.7.5a)
- Advice** Slight engine oil leak around sump area

MOT #15 2016-03-07 15:34

MOT test number 845793588702

Result ✓ Passed

- Advice** Front Headlamp deteriorated but light output not reduced Both (1.7.5a)

MOT #14 2016-03-02 15:27

MOT test number 999291798850

Result ✗ Failed

- Fail** Nearside Front Steering rack gaiter insecure (2.2.D.2d)
- Advice** Front Headlamp deteriorated but light output not reduced Both (1.7.5a)
- Fail** Offside Front Steering rack gaiter insecure (2.2.D.2d)



MOT #13 2015-03-06 09:13

MOT test number 835055365091

Result ✔ Passed

- Notice** Near side front tyre damage to side wall , not showing coards
- Notice** Rear exhaust bracket broken
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Headlamp patterns deteriorating
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #12 2015-03-03 11:19

MOT test number 885482365074

Result ✘ Failed

- Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Headlamp patterns deteriorating
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Near side front tyre damage to side wall , not showing coards
- Notice** Rear exhaust bracket broken



MOT #11 2014-03-06 10:55

MOT test number 398875364069

Result ✓ Passed

Notice Both headlight aims slightly deteriorated

MOT #10 2013-03-01 09:56

MOT test number 437040663025

Result ✓ Passed

Notice Top engine cover insecure

MOT #9 2013-02-28 12:12

MOT test number 619549853062

Result ✗ Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Notice Top engine cover insecure

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Rear fog lamp not working (1.3.2b)

MOT #8 2012-03-06 15:10

MOT test number 649906762098

Result ✓ Passed

Notice Offside front brake hose slightly twisted

Notice Both rear wheels slightly buckled



MOT #7 2012-03-06 15:10

MOT test number 627126462028

Result ✗ Failed

Pass with rectification Offside Rear Registration plate lamp not working (1.1.C.1d)

Notice Offside front brake hose slightly twisted

Notice Both rear wheels slightly buckled

MOT #6 2011-03-07 10:52

MOT test number 649686361089

Result ✓ Passed

MOT #5 2011-03-07 10:52

MOT test number 685956861068

Result ✗ Failed

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

MOT #4 2010-03-08 16:50

MOT test number 590767960007

Result ✓ Passed

MOT #3 2009-03-02 09:30

MOT test number 791911869049

Result ✓ Passed

MOT #2 2008-03-06 17:01

MOT test number 383086168030

Result ✓ Passed



MOT #1	2007-02-20 15:05
MOT test number	110411957036
Result	✓ Passed




Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	WJ04HJG
Plate since	2019-09-29
Current registration	WJ04HJG
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-03-08
Last registration	2021-02-25
Complete history	See info



Registration #1	2004-03-08	22 mi
Registration #2	2007-02-20	28.060 mi
Registration #3	2008-03-06	38.303 mi
Registration #4	2009-03-02	45.323 mi
Registration #5	2010-03-08	51.563 mi
Registration #6	2011-03-07	56.721 mi
Registration #7	2012-03-06	61.748 mi
Registration #8	2013-02-28	66.877 mi
Registration #9	2013-03-01	66.877 mi
Registration #10	2014-03-06	71.658 mi
Registration #11	2015-03-03	77.064 mi
Registration #12	2015-03-03	77.064 mi
Registration #13	2015-03-03	77.064 mi
Registration #14	2015-03-03	77.064 mi
Registration #15	2015-03-03	77.064 mi
Registration #16	2015-03-03	77.064 mi
Registration #17	2015-03-03	77.064 mi
Registration #18	2015-03-03	77.064 mi
Registration #19	2015-03-03	77.064 mi
Registration #20	2015-03-03	77.064 mi
Registration #21	2015-03-03	77.064 mi
Registration #22	2015-03-03	77.064 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1783 mm
Height	1558 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1523 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	4A71795