





report date: 2024-03-28

General information

Make	RENAULT
Model	ZOE DYNAMIQUE NAV
Colour	White
Year of manufacture	2016
Top speed	84 mph
0 - 60 mph	13.5 seconds
Gearbox	1 speed automatic

Engine & fuel consumption

Power	91 BHP
Max. torque	220 Nm at 2.500 rpm
Fuel type	Electricity



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-08

Pictures 34

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-03-30
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	10
Total items failed	1

MOT #9	2024-03-18 13:37
MOT test number	629793477475
Result	✓ Passed
Next expiry date	2025-03-30

MOT #8	2024-03-15 08:43
MOT test	number 226489758508
Result	★ Failed
MAJOR	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2m and bald on inner edge (5.2.3 (e))
MAJOR and bald o	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords on inner edge (5.2.3 (d) (i))

MOT #7	2023-03-23 11:23
MOT test number	186742631145
Result	✓ Passed
MOT #6	2023-03-23 11:23
MOT test number	419084644181
Result	★ Failed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #5 2022-03-31 11:06

MOT test number 462828037532

MOT #4 2021-03-05 09:07

MOT test number 756304224045

Result

Passed

MOT #3 2020-03-16 12:35

MOT test number 507896687736

Result
✓ Passed

MOT #2 2020-03-13 15:58

MOT test number 870042042229

Result X Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #1 2019-03-15 10:18

MOT test number 337991022547

Result
✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status

Days left

MOT expiry date

See MOT history

Valid until 1 April

338

MOT expiry date

See MOT history

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner mistory	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	AIN
Plate since	
Current registration	UK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combont info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-03-18
Last registration	2024-03-18
Complete history	See info



Registration #1	2016-03-18	21 mi
Registration #2	2019-03-15	12.031 mi
Registration #3	2020-03-13	15.197 mi
Registration #4	2020-03-16	15.197 mi
Registration #5	2021-03-05	16.332 mi
Registration #6		0.00 44
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		10.777 esc

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	89%
Children	80%
Pedestrian	66%
Safety systems	85%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1730 mm
Height	1562 mm
Length	4084 mm
Wheel base	2588 mm
Kerb weight	1468 kg
Max. allowed weight	1965 kg

Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
Number of axles Carcheck.co.uk	2 page 11/1