



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO AUTHENTIQUE 16V
Colour	Grey
Year of manufacture	2004
Top speed	101 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	95 BHP
Max. torque	148 Nm at 3.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.3 mpg
CO2 emission	190 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-03-18
Pictures	12
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2025-03-23
MOT pass rate	75 %
MOT passed	18
Failed MOT tests	6
Total advice items	28
Total items failed	12

MOT #24	2024-03-21 15:55
MOT test number	133490394851
Result	✓ Passed
Next expiry date	2025-03-23

MOT #23	2023-03-21 11:30
MOT test number	783857329185
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge and perished (5.2.3 (e))

MOT #22	2022-03-24 11:34
MOT test number	108543743281
Result	✓ Passed
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Slight exhaust leak rear box
Advice	Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))

**MOT #21**

2021-01-11 10:38

MOT test number

732580008836

Result

✓ Passed

- Advice** Brake servo rusty
- Advice** Play in steering rack inner joint(s)
- Advice** Rear seat belts not checked (dog box fitted)
- Advice** Front brake pads over half worn

MOT #20

2021-01-06 15:31

MOT test number

451545457738

Result

✗ Failed

- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Rear seat belts not checked (dog box fitted)
- Fail** Hazard warning switch inoperative (4.4.2 (a) (ii))
- Advice** Front brake pads over half worn
- Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Offside Obligatory mirror missing (3.3 (a))
- Advice** Brake servo rusty
- Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Play in steering rack inner joint(s)

MOT #19

2020-01-02 14:41

MOT test number

361589970475

Result

✓ Passed

- Advice** Rear Passenger seat(s) missing at time of test

**MOT #18** 2019-03-05 09:39**MOT test number** 973466693775**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front steering rack boot perished**MOT #17** 2018-03-16 09:18**MOT test number** 278450531571**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #16** 2018-03-15 11:49**MOT test number** 200894366466**Result** ✗ Failed**Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #15** 2017-03-14 14:48**MOT test number** 256932665419**Result** ✓ Passed**MOT #14** 2017-03-14 14:48**MOT test number** 944408123144**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)

**MOT #13** 2016-03-17 11:55**MOT test number** 425691070305**Result** ✓ Passed**MOT #12** 2016-03-17 09:13**MOT test number** 444506468359**Result** ✗ Failed**Fail** Nearside Front Steering rack gaiter split (2.2.D.2d)**MOT #11** 2015-03-11 10:30**MOT test number** 548080475061**Result** ✓ Passed**Advice** Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #10** 2014-03-05 16:40**MOT test number** 127284064415**Result** ✓ Passed**MOT #9** 2013-03-06 15:51**MOT test number** 989405863022**Result** ✓ Passed**Advice** Offside brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2013-03-06 12:53**MOT test number** 215835163042**Result** ✗ Failed**Advice** Offside brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Nearside brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Nearside Steering rack gaiter split (2.2.D.2d)**MOT #7** 2012-03-07 18:08**MOT test number** 559867962090**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #6** 2011-03-02 18:56**MOT test number** 186381061044**Result** ✓ Passed**Notice** Tyres are starting to perish on edges**MOT #5** 2010-03-08 10:06**MOT test number** 523217560056**Result** ✓ Passed**MOT #4** 2009-03-16 16:49**MOT test number** 900515679024**Result** ✓ Passed



MOT #3	2009-03-16 11:19
MOT test number	172475079415
Result	✗ Failed
Fail	Nearside Front Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)
Advice	Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

MOT #2	2008-03-27 10:54
MOT test number	110217788403
Result	✓ Passed

MOT #1	2007-10-22 10:44
MOT test number	393255697205
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
23 March 2025

Tax status	Valid until 1 October
Days left	154
MOT expiry date	23 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	AY54XGZ
Plate since	2019-09-28
Current registration	AY54XGZ
Plate since	2019-09-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2004-11-25
Last registration	2024-03-21
Complete history	See info



Registration #1	2004-11-25	15 mi
Registration #2	2007-10-22	8.793 mi
Registration #3	2008-03-27	9.347 mi
Registration #4	2009-03-16	14.848 mi
Registration #5	2009-03-16	14.848 mi
Registration #6	2010-03-08	20.809 mi
Registration #7	2011-03-02	24.435 mi
Registration #8	2012-03-07	27.183 mi
Registration #9	2013-03-06	29.484 mi
Registration #10	2013-03-06	29.484 mi
Registration #11	2014-03-05	32.071 mi
Registration #12	2015-03-11	35.050 mi
Registration #13	2016-03-17	36.928 mi
Registration #14	2016-03-17	36.928 mi
Registration #15	2016-03-17	36.928 mi
Registration #16	2016-03-17	36.928 mi
Registration #17	2016-03-17	36.928 mi
Registration #18	2016-03-17	36.928 mi
Registration #19	2016-03-17	36.928 mi
Registration #20	2016-03-17	36.928 mi
Registration #21	2016-03-17	36.928 mi
Registration #22	2016-03-17	36.928 mi
Registration #23	2016-03-17	36.928 mi
Registration #24	2016-03-17	36.928 mi
Registration #25	2016-03-17	36.928 mi
Registration #26	2016-03-17	36.928 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1672 mm
Height	1855 mm
Length	4035 mm
Wheel base	2600 mm
Kerb weight	1120 kg
Max. allowed weight	1645 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D009929