





report date: 2024-03-28

#### General information

Make	RENAULT	
Model	MODUS EXPRESSION DCI 80	
Colour	Blue	
Year of manufacture	2004	
Top speed	104 mph	
0 - 60 mph	14.9 seconds	
Gearbox	5 speed Manual	

### Engine & fuel consumption

Power	80 BHP
Max. torque	185 Nm at 2.000 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	122 g/km
CO2 label	D



CarCheck.co.uk page 1/13



MOT history

MOT expiry date	2021-06-07
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	27
Total items failed	17

MOT #19	2020-06-08 15:17
MOT test number	278446996834
Result	✓ Passed
Next expiry date	2021-06-07

MOT #	18	2020-05-26 11:51
<b>MOT test number</b> 7129442052		712944205226
Result		<b>×</b> Failed
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail	Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))	
Fail	Offside Rear Service brake excessively binding (1.2.1 (f))	
Fail	Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2	.2.2 (b))
Fail	Front Sub-frame corroded and seriously weakened (5.3.3 (b) (i))	

MOT #17	2019-05-31 08:25
MOT test	number 952213829652
Result	✓ Passed
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 2/13



MOT #16 2018-06-05 10:56

MOT test number 437835836070

Result Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15 2018-06-01 11:29

MOT test number 782591343147

Result × Failed

Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Stop lamp(s) all not working (4.3.1 (a) (iii))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

CarCheck.co.uk page 3/13



Fail

**Advice** 

**RF54LYO** 

report date: 2024-03-28

MOT #14

MOT test number

177148698168

Result

Advice Both front tyres worn inside edges

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Result

Fail Front passenger door cannot be opened from outside the vehicle (6.2.B.1b)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Both front tyres worn inside edges

 MOT #12
 2016-05-27 12:31

 MOT test number
 563977834437

 Result
 ✓ Passed

 MOT #11
 2016-05-06 11:02

 MOT test number
 136991366390

 Result
 X Failed

Front Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)

MOT #10

MOT test number

768179015123

Result

Notice Child seat fitted not allowing full inspection of adult belt

Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 4/13



RF54LYO

report date: 2024-03-28

MOT #9

MOT test number

467516804120

Result

Notice Nail in nearside front tyre

MOT #8

MOT test number

287911023483

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT** #7 2013-04-24 16:29 467244513114 **MOT** test number Result × Failed Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Nearside Front Track rod end ball joint has excessive play (2.2.B.1f) **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) Notice Suggest wheel alignment check Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Offside Front Track rod end ball joint has excessive play (2.2.B.1f)

MOT #6

MOT test number

678083022103

Result

Notice Some damage to n/s front tyrewall not RFR at time of test

 MOT #5
 2011-04-19 17:24

 MOT test number
 405579901154

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



MOT #4 2011-04-19 12:04

**MOT test number** 225629801164

**Result** X Failed

Fail Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Brakes imbalanced across an axle (3.7.B.5b)

MOT #3 2010-04-30 09:16

MOT test number 272250520117

Result \square Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2009-04-16 12:36

MOT test number 223596709177

Result 

Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #1 2008-04-24 12:19

**MOT test number** 850405418126

**Result** 
✓ Passed

CarCheck.co.uk page 6/13



#### Tax & MOT check



Expired: 7 June 2021 X MOT

Expired at 8 December 2020

Days left 1238 days too late

MOT expiry date 7 June 2021

Full MOT history See MOT history

#### Tax calculation

**Tax status** 

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

•		
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		AULT
********		
***************************************		
	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2004-11-23
Last registration	2020-06-08
Complete history	See info



2004-11-23	23 mi
2008-04-24	31.828 mi
2009-04-16	37.822 mi
2010-04-30	47.980 mi
2011-04-19	59.048 mi
2011-04-19	59.048 mi
2012-05-02	66.925 mi
2013-04-24	72.814 mi
2013-05-01	72.969 mi
2014-04-16	82.593 mi
	9.70 es
	11.777 es
	9.70 es
	11.777 es
	9.70 es
	11.777 es
	9.70 es
	11.777 es
	70,777 es
	2008-04-24 2009-04-16 2010-04-30 2011-04-19 2011-04-19 2012-05-02 2013-04-24 2013-05-01 2014-04-16

More info >

CarCheck.co.uk page 12/13



### Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	2026 mm
Height	1467 mm
Length	4500 mm
Wheel base	2686 mm
Max. allowed weight	1815 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

**Engine number** 

D228294