



report date: 2024-03-28

General information

Make	VOLVO
Model	C70 T5 COLLECTION
Colour	Grey
Year of manufacture	2005
Top speed	143 mph
0 - 60 mph	8.0 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	330 Nm at 5.100 rpm
Engine capacity	2.319 cc
Cylinders	5
Fuel type	Petrol
Consumption city	17.7 mpg
Consumption extra urban	35.3 mpg
Consumption combined	25.9 mpg
CO2 emission	261 g/km
CO2 label	M







Internet history

Entry 1

Date	2021-09-01
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-04-03
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	60
Total items failed	7

MOT #20 2023-04-04 10:35

MOT test number 787769641681

Result ✓ Passed

Next expiry date 2024-04-03

- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Play in steering rack inner joint(s) n/s and o/s
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement inner bushes (5.3.4 (a) (i))

MOT #19 2023-04-04 10:35

MOT test number 832072836005

Result ✗ Failed

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement inner bushes (5.3.4 (a) (i))
- Advice** Play in steering rack inner joint(s) n/s and o/s
- Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Pass with rectification** Headlamp aim too low and too far to the right. (4.1.2 (a))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #18**

2022-02-02 16:19

MOT test number

260729888286

Result

✓ Passed

Advice Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #17**

2020-11-25 17:29

MOT test number

410957883265

Result

✓ Passed

Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front (5.3.4 (a) (i))**Advice** Front discs are corroded**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Wiper blades slightly smearing

**MOT #16**

2020-11-20 12:22

MOT test number

514574079200

Result**✗ Failed****Advice** Front discs are corroded**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MAJOR** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front (5.3.4 (a) (i))**MAJOR** Nearside Side repeater incorrect colour (4.4.3 (a))**Advice** Front tyres are heavily scrubbed, tracking may need adjusting**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Play in steering rack inner joint(s)**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 3.8mm (5.2.3 (e))**MAJOR** Brake lever has insufficient reserve travel hand brake (1.1.2 (a))**Advice** Wiper blades slightly smearing**MAJOR** Offside Side repeater incorrect colour (4.4.3 (a))**MOT #15**

2019-11-19 10:36

MOT test number

182390712698

Result**✓ Passed****Advice** Offside Front Play in steering rack inner joint(s)

**MOT #14** 2018-11-16 10:40**MOT test number** 113895650811**Result** ✓ Passed**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #13** 2017-11-15 10:48**MOT test number** 889130223361**Result** ✓ Passed**Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #12** 2016-11-16 10:56**MOT test number** 122603445892**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2015-10-29 11:52**MOT test number** 493731466812**Result** ✓ Passed**MOT #10** 2014-11-22 13:02**MOT test number** 625866924336**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Upper engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)

**MOT #9** 2013-11-08 13:24**MOT test number** 548562813361**Result** ✓ Passed**MOT #8** 2013-01-29 15:17**MOT test number** 887479023075**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Lower Suspension arm has slight play in a track control arm inner bush (2.5.B.2b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Rear brake discs corroded & lightly pitted
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #7 2013-01-29 10:08**MOT test number** 648649023020**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Lower Suspension arm has slight play in a track control arm inner bush (2.5.B.2b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Notice** Rear brake discs corroded & lightly pitted
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Rear Direction indicator incorrect colour (1.4.A.2f)

**MOT #6** 2012-01-19 09:22**MOT test number** 368409812005**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm has slight play in a track control arm inner bush (2.5.B.2b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #5** 2011-02-01 14:19**MOT test number** 119522231077**Result** ✓ Passed**MOT #4** 2011-02-01 10:43**MOT test number** 145952431426**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** N/S/F tyre has several cuts in the sidewall not deep enough to expose ply or cords**MOT #3** 2010-02-02 12:25**MOT test number** 331223730057**Result** ✓ Passed**MOT #2** 2009-01-26 12:51**MOT test number** 174036429071**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2008-02-04 16:58
MOT test number	394675838061
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-03-30
Last registration	2023-04-04
Complete history	See info



Registration #1	2005-03-30	22 mi
Registration #2	2008-02-04	16.105 mi
Registration #3	2009-01-26	21.004 mi
Registration #4	2010-02-02	25.211 mi
Registration #5	2011-02-01	28.714 mi
Registration #6	2011-02-01	28.714 mi
Registration #7	2012-01-19	35.290 mi
Registration #8	2013-01-29	44.830 mi
Registration #9	2013-01-29	44.838 mi
Registration #10	2013-11-08	51.435 mi
Registration #11	2014-11-22	55.918 mi
Registration #12	2015-05-20	56.377 mi
Registration #13	2015-05-20	56.377 mi
Registration #14	2015-05-20	56.377 mi
Registration #15	2015-05-20	56.377 mi
Registration #16	2015-05-20	56.377 mi
Registration #17	2015-05-20	56.377 mi
Registration #18	2015-05-20	56.377 mi
Registration #19	2015-05-20	56.377 mi
Registration #20	2015-05-20	56.377 mi
Registration #21	2015-05-20	56.377 mi
Registration #22	2015-05-20	56.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1820 mm
Height	2660 mm
Length	4720 mm
Wheel base	1420 mm
Kerb weight	1565 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Engine number	3650478