





report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE V6 SPORT
Colour	Grey
Year of manufacture	-
Top speed	143 mph
0 - 60 mph	7.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	231 BHP	
Max. torque	284 Nm at 3.000 rpm	
Cylinders	6	
Fuel type	Petrol	
Consumption city	18.7 mpg	
Consumption extra urban	36.4 mpg	
Consumption combined	27.0 mpg	



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-09-22

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



✓ Passed

MOT history

Result

Fail

MOT #18 2018-04-24 12:19

MOT test number 583551216961

Next expiry date 2019-04-23

Advice Nearside Rear tyre worn low on edges

Advice Age cracking in both rear tyres

MOT #17 2017-03-29 08:17

MOT test number 239041713169

Advice Nearside Rear tyre worn low on edges

MOT #16 2017-03-28 14:45

MOT test number 489352788871

Result × Failed

Advice Nearside Rear tyre worn low on edges

Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #15 2016-03-01 11:52

MOT test number 704325050761

Result \(\sqrt{Passed} \)

Advice Corrosion in offside front unersill

Advice Advanced corrosion in offside outer sill

Advice Nearside Rear tyre worn low on inner edge

MOT #14 2015-01-30 12:46

MOT test number 909830435096

Result \(\sqrt{Passed} \)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 3/12



MOT #13 2015-01-27 12:11

MOT test number 946677625004

Result X Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #12 2013-11-05 11:02

MOT test number 217009303353

Result ✓ Passed

MOT #11 2013-10-24 09:28

MOT test number 765937693249

Result X Failed

Fail Offside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)

MOT #10 2012-10-11 11:26

MOT test number 459745682271

Result

Passed

Notice Corrosion in offside outer sill

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Notice Offside front tyre generally worn on inner edge

MOT #9 2011-08-26 14:31

MOT test number 346978631430

Result ✓ Passed

CarCheck.co.uk page 4/12



MOT #8

MOT test number

605570231214

Result

Fail Anti-lock braking system warning lamp sequence is incorrect (3.4.1d)

Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

MOT #7	2010-06-03 08:07
MOT test number	201174250145
Result	✓ Passed
Notice Rear brake pads worn	

MOT #6	2009-04-08 11:46
MOT test number	174528199428
Result	✓ Passed

MOT #5	2008-04-11 10:30
MOT test number	760652108124
Result	✓ Passed

MOT #4	2007-10-31 16:26
MOT test number	711614207391
Result	✓ Passed

MOT #3	2007-10-30 07:59
MOT test number	940003707363

Result X Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

CarCheck.co.uk page 5/12



MOT #2

MOT test number

790003696253

Result

MOT #1

2006-10-20 12:11

MOT test number

754033396240

Result

Pass with rectification

Offside Front Direction indicator not working (1.4.A.2c)

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

o mile motory	
For how long did the current and previous owner(s) have this JAGUAR? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
See in this check if this JAGOAN had different humber plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2001-11-07
Last registration	2018-04-24
Complete history	See info



Registration #1	2001-11-07	8 mi
Registration #2	2006-10-20	1.996 mi
Registration #3	2007-10-30	7.802 mi
Registration #4	2007-10-31	7.802 mi
Registration #5	2008-04-11	11.312 mi
Registration #6	2009-04-08	15.063 mi
Registration #7	2010-06-03	19.604 mi
Registration #8	2011-08-18	23.462 mi
Registration #9	2011-08-26	23.491 mi
Registration #10	2012-10-11	26.873 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		71,777 ea

More info >

CarCheck.co.uk page 11/12



Dimensions & weight	D	im	en	sic	ons	&	wei	igl	ht
---------------------	---	----	----	-----	-----	---	-----	-----	----

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm

Additional information

Fuel tank capacity	61		
Fuel delivery	Multi-Point Injection		
Number of doors	4		
Number of axles	2		
Engine number	177392401WB		

CarCheck.co.uk page 12/12