



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	Black
Year of manufacture	2010
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-01-07
Pictures	16
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-04-10
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	27
Total items failed	8

MOT #162023-04-11 15:00

MOT test number248718200565

Result✓ Passed

Next expiry date2024-04-10

Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Coolant leak
Advice	Rear Outer Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated slight sweat of grease (6.1.7 (g) (i))

**MOT #15**

2023-04-08 09:44

**MOT test number**

283407127466

**Result****✗ Failed**

**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated slight sweat of grease (6.1.7 (g) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Rear Outer Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))

**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MAJOR** Offside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))

**Advice** Coolant leak

**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #14**

2023-02-14 16:27

**MOT test number**

243035945625

**Result****✗ Failed**

**MAJOR** Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Coolant leak

**MOT #13**

2022-01-11 14:29

**MOT test number**

268200554633

**Result****✓ Passed**

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12** 2021-03-23 08:54**MOT test number** 395670495534**Result** ✓ Passed**MOT #11** 2020-03-17 11:37**MOT test number** 680663791466**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #10** 2019-03-21 09:44**MOT test number** 930749727435**Result** ✓ Passed**MOT #9** 2018-03-19 16:36**MOT test number** 982669149136**Result** ✓ Passed**MOT #8** 2018-03-19 09:48**MOT test number** 705721867241**Result** ✗ Failed**Fail** Offside Side repeater not working (1.4.A.2c)**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

**MOT #7** 2017-03-15 16:12**MOT test number** 834483369637**Result** ✓ Passed**Advice** Engine bay covers and under body trays**MOT #6** 2017-03-15 12:00**MOT test number** 221948355423**Result** ✗ Failed**Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Advice** Engine bay covers and under body trays**MOT #5** 2016-03-03 11:19**MOT test number** 443454628246**Result** ✓ Passed**MOT #4** 2015-02-25 10:01**MOT test number** 557656455037**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-03-25 14:47**MOT test number** 487994284034**Result** ✓ Passed**MOT #2** 2013-08-13 14:22**MOT test number** 325705123471**Result** ✓ Passed



MOT #1	2013-08-13 12:25
MOT test number	159315923219
Result	✗ Failed
Fail	Front Supplementary Restraint System warning lamp indicates a fault (5.4.2)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-29
Last registration	2023-04-11
Complete history	<a href="#">See info</a>



Registration #1	2010-09-29	12 mi
Registration #2	2013-08-13	30.061 mi
Registration #3	2013-08-13	30.061 mi
Registration #4	2014-03-25	33.199 mi
Registration #5	2015-02-25	40.185 mi
Registration #6	2016-03-03	44.867 mi
Registration #7	2017-03-15	49.969 mi
Registration #8	2017-03-15	49.969 mi
Registration #9	2018-03-19	59.074 mi
Registration #10	2019-03-20	65.277 mi
Registration #11	2019-03-20	65.277 mi
Registration #12	2019-03-20	65.277 mi
Registration #13	2019-03-20	65.277 mi
Registration #14	2019-03-20	65.277 mi
Registration #15	2019-03-20	65.277 mi
Registration #16	2019-03-20	65.277 mi
Registration #17	2019-03-20	65.277 mi
Registration #18	2019-03-20	65.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1299 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	181935