



report date: 2024-03-29

General information

Make	MAZDA
Model	5 TS2
Colour	Black
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	144 BHP
Max. torque	185 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.4 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-04
Pictures	34
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #15	2022-08-17 09:58
MOT test number	832818337092
Result	✓ Passed
Next expiry date	2023-09-07
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #14	2022-08-17 09:58
MOT test number	874411237065
Result	✗ Failed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #13	2021-09-08 16:09
MOT test number	752466093824
Result	✓ Passed

MOT #12	2021-09-08 14:31
MOT test number	935970229923
Result	✗ Failed
Fail	Rear fog lamp tell-tale missing (4.9.1 (a) (ii))
Fail	Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #11**

2019-02-01 12:48

MOT test number

460873793999

Result

✓ Passed

- Advice** Oil leak, but not excessive slight gearbox oil leak (8.4.1 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Exhaust mounting defective 1 rear mounting bracket broke (6.1.2 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge wearing (5.2.3 (e))

MOT #10

2019-01-28 11:48

MOT test number

879960127687

Result

✗ Failed

- Fail** Nearside Windscreen in an unacceptable condition n/s screen has damage more than 40mm in swept area and a small stone chip in zone a (3.2 (c) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Exhaust mounting defective 1 rear mounting bracket broke (6.1.2 (a))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Front Anti-roll bar pin or bush excessively worn d bushes worn (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge wearing (5.2.3 (e))
- Advice** Oil leak, but not excessive slight gearbox oil leak (8.4.1 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #9** 2018-01-29 14:39**MOT test number** 894871948659**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #8** 2018-01-27 11:15**MOT test number** 105230656633**Result** ✗ Failed**Fail** Exhaust system not adequately supported back box. (7.1.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #7** 2017-02-01 16:34**MOT test number** 808308812833**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Track rod end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)

**MOT #6**

2017-01-30 09:48

MOT test number

697994035406

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to the legal limit 3mm 205/55/16 (4.1.E.1)
- Fail** Rear fog lamp not working (1.3.2b)
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Nearside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Offside Rear coil spring broken (2.4.C.1a)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice** Offside Front Tyre worn close to the legal limit 2.5mm 205/55/16 (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Fail** Offside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)

MOT #5

2015-09-30 12:25

MOT test number

969120352241

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4

2014-09-10 11:25

MOT test number

756263554203

Result**✓ Passed**



MOT #3	2013-07-02 11:43
MOT test number	516103083140
Result	✓ Passed
MOT #2	2012-06-29 12:52
MOT test number	635321982126
Result	✓ Passed
MOT #1	2011-06-27 15:06
MOT test number	135918571141
Result	✓ Passed



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	MM08KVW
Plate since	2019-03-29
Current registration	MM08KVW
Plate since	2019-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-06-30
Last registration	2022-08-17
Complete history	See info



Registration #1	2008-06-30	10 mi
Registration #2	2011-06-27	24.834 mi
Registration #3	2012-06-29	33.371 mi
Registration #4	2013-07-02	42.683 mi
Registration #5	2014-09-10	52.557 mi
Registration #6	2015-09-30	62.291 mi
Registration #7	2017-01-30	77.699 mi
Registration #8	2017-02-01	77.720 mi
Registration #9	2018-01-27	86.104 mi
Registration #10	2019-01-27	95.377 mi
Registration #11	2019-01-27	95.377 mi
Registration #12	2019-01-27	95.377 mi
Registration #13	2019-01-27	95.377 mi
Registration #14	2019-01-27	95.377 mi
Registration #15	2019-01-27	95.377 mi
Registration #16	2019-01-27	95.377 mi
Registration #17	2019-01-27	95.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4505 mm
Wheel base	2750 mm
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	LF10510608