





report date: 2024-03-28

General information

Make	FORD	
Model	S-MAX TITANIUM TDCI	
Colour	Black	
Year of manufacture	2012	
Top speed	124 mph	
0 - 100 km/h	11.1 seconds	
0 - 60 mph	10.4 seconds	
Gearbox	6 speed automatic	

Engine & fuel consumption

Power	103 kW / 140 HP / 161 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/12



Internet history


Entry 1

Date 2021-10-20

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-07
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	18
Total items failed	3

MOT #11	2023-11-08 14:05
MOT test number	924371085805
Result	✓ Passed
Next expiry date	2024-11-07
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated Pin hole (6.1.7 (g) (i))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #10	2023-11-01 14:07
MOT test number	740850796312
Result	× Failed
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deterior (g) (i))	iorated Pin hole (6.1.7
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to re And bald inner edge (5.2.3 (d) (i))	each the ply or cords
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Fail Offside Front Tyre has ply or cords exposed Inner edge (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2022-10-20 14:49

MOT test number 869977268561

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm and bald inner edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm and bald inner edge (5.2.3 (e))

MOT #8 2021-10-13 11:06

MOT test number 844161520579

Result ✓ Passed

MOT #7 2021-05-14 14:50

MOT test number 813533188992

Result \rightarrow Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2021-05-11 08:24

MOT test number 458476892225

Result X Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #5 2019-06-24 08:35

MOT test number 956896381375

Result
✓ Passed

Advice Rear trailing arm bushes deteriorated

Advice Rear coil springs corroded

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4		2018-07-17 12:01
MOT test	number	848215458090
Result		✓ Passed
Advice (i))	Offside Rear Suspension arm pin or bush worn but not resulting in excessive	ve movement (5.3.4 (a)
Advice (a) (i))	Nearside Rear Suspension arm pin or bush worn but not resulting in excess	sive movement (5.3.4
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #3	2017-07-13 14:56
MOT test number	945341255811
Result	✓ Passed
MOT #2	2016-07-04 08:51
MOT test number	260663910283
Result	✓ Passed
MOT #1	2015-07-03 10:05
MOT test number	969494385148
Result	✓ Passed
Notice Windscreen washers partially blocked	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	7 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

ET12EOP

report date: 2024-03-28

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

More info >

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-07-23
Last registration	2023-11-08
Complete history	See info



Registration #1	2012-07-23	14 mi
Registration #2	2015-07-03	45.874 mi
Registration #3	2016-07-04	54.194 mi
Registration #4	2017-07-13	62.750 mi
Registration #5	2018-07-17	73.306 mi
Registration #6	2019-06-24	81.145 mi
Registration #7	2021-05-11	91.264 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1884 mm
Height	1764 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1631 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 12/1