



report date: 2024-03-28

## General information

Make	VOLKSWAGEN
Model	TIGUAN SE TDI DSG 140
Colour	Blue
Year of manufacture	2009
Top speed	123 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-03
Pictures	21
Listing price	<a href="#">View report</a>



source: theaa.com



## MOT history

MOT expiry date	2024-05-24
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	50
Total items failed	4

MOT #15	2023-05-09 15:14
MOT test number	311096252469
Result	✓ Passed
Next expiry date	2024-05-24

MOT #14	2023-05-09 07:24
MOT test number	579723743946
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Nearside rear tyre tread on 3mm, minimum is 1.6mm...
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2022-05-18 08:06
MOT test number	726526629588
Result	✓ Passed
Advice	Nearside Front Tyre on 3mm
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Tyre on 3mm

**MOT #12**

2021-05-25 14:55

**MOT test number**

102059141214

**Result**

✓ Passed

**Advice** Front Shock absorbers light misting of oil or has limited damping effect both (5.3.2 (b))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #11**

2020-09-21 08:50

**MOT test number**

474095361229

**Result**

✓ Passed

**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #10**

2019-09-30 14:48

**MOT test number**

953885330097

**Result**

✓ Passed

**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated leaking grease (6.1.7 (g) (i))**Advice** Rear Prop shaft flexible coupling slightly deteriorated damper deteriorated (6.1.7 (d) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9**

2019-09-30 08:04

**MOT test number**

428334598204

**Result****✗ Failed**

- Advice** Rear Prop shaft flexible coupling slightly deteriorated damper deteriorated (6.1.7 (d) (i))
- Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated leaking grease (6.1.7 (g) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #8**

2018-09-20 10:30

**MOT test number**

110564598551

**Result****✓ Passed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #7**

2018-09-20 10:30

**MOT test number**

647363965498

**Result****✗ Failed**

- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #6**

2017-09-25 12:17

**MOT test number**

404671811097

**Result****✓ Passed**

- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #5**

2016-09-21 08:41

**MOT test number**

621292545192

**Result****✓ Passed**

- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2015-09-22 11:55**MOT test number** 573061662240**Result** ✓ Passed**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**MOT #3** 2014-09-18 15:15**MOT test number** 558961264242**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #2** 2013-10-01 13:47**MOT test number** 828484073275**Result** ✓ Passed**MOT #1** 2012-09-11 12:32**MOT test number** 579895952236**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
24 May 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	24 May 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>KY59XWF</b>
Plate since	2024-03-28
Current registration	 <b>KY59XWF</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-10-02
Last registration	2023-05-09
Complete history	<a href="#">See info</a>



Registration #1	2009-10-02	24 mi
Registration #2	2012-09-11	23.650 mi
Registration #3	2013-10-01	34.471 mi
Registration #4	2014-09-18	43.603 mi
Registration #5	2015-09-22	52.973 mi
Registration #6	2016-09-21	61.360 mi
Registration #7	2017-09-25	69.108 mi
Registration #8	2018-09-20	74.938 mi
Registration #9	2018-09-20	74.938 mi
Registration #10	2019-05-20	75.277 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi
Registration #13	2019-05-20	75.277 mi
Registration #14	2019-05-20	75.277 mi
Registration #15	2019-05-20	75.277 mi
Registration #16	2019-05-20	75.277 mi
Registration #17	2019-05-20	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Max. allowed weight	2290 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

**Engine number**

BKD C66894