





General information

| Make | VOLKSWAGEN |
|---------------------|-------------------|
| Model | POLO GTI TSI DSG |
| Colour | Blue |
| Year of manufacture | 2019 |
| Top speed | 147 mph |
| 0 - 100 km/h | 6.7 seconds |
| 0 - 60 mph | 6.7 seconds |
| Gearbox | 6 speed Semi Auto |

Engine & fuel consumption

| Power | 147 kW / 200 HP / 197 BHP |
|-------------------------|---------------------------|
| Max. torque | 320 Nm at 1.500 rpm |
| Engine capacity | 1.984 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 36.7 mpg |
| Consumption extra urban | 57.7 mpg |
| Consumption combined | 47.9 mpg |
| CO2 emission | 138 g/km |
| CO2 label | E |







Internet history

Entry 1

Date Pictures 2022-06-29

12

Listing price

View report



source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-06-05 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 0 |
| Total items failed | 2 |

| MOT #4 | 2023-05-25 10:37 |
|------------------|------------------|
| MOT test number | 905272093342 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-05 |

| MOT #3 | 2022-06-06 20:44 |
|-----------------|------------------|
| MOT test number | 845205053004 |
| Result | ✓ Passed |

| MOT #2 | 2022-06-06 18:41 |
|---|------------------|
| MOT test number | 130654365199 |
| Result | 🗙 Failed |
| Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) | |
| Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c)) | |
| | |

| MOT #1 | 2022-03-23 14:11 |
|-----------------|------------------|
| MOT test number | 486823755381 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed | ✓ MOT |
|------------------|--|
| 1 September 2024 | Expires: 5 June 2024 Valid until 1 September |
| | |
| Days left | 124 |
| MOT expiry date | 5 June 2024 |
| Full MOT history | See MOT histor |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | н |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | FEED ON |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Date | |
| Date | OLE I |
| Category | AM |
| Туре | |

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.700 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10 700 |





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ******** | |
|--|-------------|
| | |
| | |
| ********** | |
| ANALY AND A ANALY ANY ANY ANY ANY ANY ANY ANY ANY ANY AN | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| | |
| Plate sites | |





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2019-05-30 |
| Last registration | 2023-05-25 |
| Complete history | See info |



| Registration #1 | 2019-05-30 | 15 mi |
|-----------------|------------|------------|
| Registration #2 | 2022-03-23 | 24.833 mi |
| Registration #3 | 2022-06-06 | 24.900 mi |
| Registration #4 | | 11.177 esi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 mi |





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | *** |
|----------------|-----------------|
| Adult | 96% |
| Children | 85% |
| Pedestrian | 76% |
| Safety systems | 59% |
| Overall rating | 82% |
| Video | see crash video |



| Dimensions & weight | |
|------------------------|------------------|
| Width | 1946 mm |
| Height | 1438 mm |
| Length | 4067 mm |
| Wheel base | 2548 mm |
| Kerb weight | 1280 kg |
| Max. allowed weight | 1780 kg |
| Additional information | |
| Fuel tank capacity | 40 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| CarCheck.co.uk | page 10/1 |

| Number of seats | 5 |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | DKZC031222 |