



report date: 2024-03-28

## General information

Make	VOLVO
Model	XC60 D5 SE AWD
Colour	Blue
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: autoonline.co.uk



## MOT history

MOT expiry date	2025-01-04
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	40
Total items failed	5

MOT #12	2023-12-18 11:30
MOT test number	497385766834
Result	✓ Passed
Next expiry date	2025-01-04
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #11	2022-12-21 12:32
MOT test number	454617086171
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2021-12-20 15:47
MOT test number	250911052670
Result	✓ Passed
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Outer side wall cut (5.2.3 (d) (i))

**MOT #9** 2021-12-17 14:04**MOT test number** 342401682433**Result** ✗ Failed**Fail** Nearside Front Seat belt buckle not functioning as intended Passenger seat (7.1.2 (d))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Outer side wall cut (5.2.3 (d) (i))**Fail** Offside Front Seat belt buckle not functioning as intended Drivers seat (7.1.2 (d))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #8** 2021-01-05 12:44**MOT test number** 789671553126**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2019-08-07 12:31**MOT test number** 273461177813**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #6** 2018-08-14 08:18**MOT test number** 323428331793**Result** ✓ Passed**Advice** Front Tyre treads wearing on inner edges**Minor** Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**Advice** Nearside Rear Bumper damaged not likely to cause injury**Advice** Nearside Front Slight damage to tyre sidewall/roadwheel

**MOT #5** 2017-08-08 09:48**MOT test number** 653760138296**Result** ✓ Passed**Advice** Engine cover fitted**Advice** Undertrays fitted**MOT #4** 2016-08-15 11:47**MOT test number** 232506711951**Result** ✓ Passed**MOT #3** 2016-06-22 08:04**MOT test number** 453582823116**Result** ✓ Passed**Advice** Offside front tyre is bald on the inner edge**Advice** Offside rear trailing arm forward bush is badly seperating**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Oil level is just above minimum**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Both front tyres are worn on the inner edges**Advice** Offside front tyre is worn down to 3mm**Advice** Nearside rear trailing arm forward bush is badly seperating**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside front wheel arch liner is damaged**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)



MOT #2

2016-06-22 08:04

MOT test number

518716783305

Result

✗ Failed

- Advice

Rear Brake pad(s) wearing thin (3.5.1g)
- Advice

Offside front tyre is bald on the inner edge
- Advice

Front registration plate delaminated but not likely to be misread (6.3.1d)
- Advice

Offside rear trailing arm forward bush is badly seperating
- Advice

Oil level is just above minimum
- Pass with rectification

Offside Front Seat belt locking mechanism does not secure or release (5.2.5a)
- Advice

Both front tyres are worn on the inner edges
- Advice

Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Offside front tyre is worn down to 3mm
- Advice

Rear registration plate delaminated but not likely to be misread (6.3.1d)
- Advice

Nearside rear trailing arm forward bush is badly seperating
- Pass with rectification

Nearside Front Seat belt locking mechanism does not secure or release (5.2.5a)
- Advice

Nearside front wheel arch liner is damaged

MOT #1

2015-07-14 16:12

MOT test number

606295395120

Result

✓ Passed

- Advice

Offside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)
- Notice

Cut in N/S/F tyre - no cords exposed
- Notice

N/S/F wheel arch liner damaged



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
4 January 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	4 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-01
Last registration	2023-12-18
Complete history	<a href="#">See info</a>



Registration #1	2011-09-01	7 mi
Registration #2	2015-07-14	38.808 mi
Registration #3	2016-06-22	44.644 mi
Registration #4	2016-06-22	44.644 mi
Registration #5	2016-08-15	45.766 mi
Registration #6	2017-08-08	53.496 mi
Registration #7	2018-08-14	60.094 mi
Registration #8	2019-05-29	65.277 mi
Registration #9	2019-05-29	65.277 mi
Registration #10	2019-05-29	65.277 mi
Registration #11	2019-05-29	65.277 mi
Registration #12	2019-05-29	65.277 mi
Registration #13	2019-05-29	65.277 mi
Registration #14	2019-05-29	65.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1883 kg
Max. allowed weight	2400 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	1047987
---------------	---------