





#### General information

Make	NISSAN
Model	NV200 E ACENTA RAPID PLUS
Colour	Blue
Year of manufacture	2014
Top speed	76 mph
Gearbox	1 speed automatic

# Engine & fuel consumption

Power	107 BHP
Max. torque	254 Nm at 10.500 rpm
Fuel type	Electricity





### Internet history


Entry 1

Date Pictures 2022-08-06

46

Listing price

View report



source: cargurus.co.uk



### MOT history

MOT expiry date	2024-08-02
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	9
Total items failed	5

MOT #10	2023-07-11 10:13
MOT test number	361764039139
Result	🗸 Passed
Next expiry date 2024-08	
Minor Nearside Rear reflector defective or damaged by up to 50% of the refl	ecting surface (4.8.1 (a) (i))

МОТ #9	2023-07-11 10:13	
MOT test number	627255643178	
Result	× Failed	
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))	
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))	
Minor Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))		

MOT #8	2022-08-03 11:17
MOT test number	220387088066
Result	✓ Passed
MOT #7	2021-07-27 14:38
MOT test number	219897032593

Result

🗸 Passed



BN64RSZ report date: 2024-03-28

MOT #	<b>#6</b>		2021-07-27 14:38
MOT t	est number		310421259991
Result	t		🗙 Failed
Pass	s with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Pass	s with rectification	Central Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #5		2020-05-06 13:41
MOT test	number	745911753350
Result		Passed
Advice	Offside Front Outer Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Vehicles internal headlight adjuster altered to recheck lights set to 0	

MOT #4	2019-05-10 17:19
MOT test number	560796727522
Result	✓ Passed
Advice Offside Front Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #3	201	.9-05-10 17:19
MOT test i	number 8	807424350425
Result		🗙 Failed
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))	
MAJOR	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (in	i))

MOT #2	2018-05-15 11:58
MOT test number	292622072424
Result	✓ Passed
Advice Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)	






MOT #1	2018-05-12 09:28
MOT test number	763181883614
Result	🗙 Failed
FailNearside Front Obligatory mirror seriously obscured affecting the rear view (8.1.2a)AdviceOffside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)	



Tax & MOT check







#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

#### Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



BN64RSZ report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-30
Last registration	2023-07-11
Complete history	See info



Registration #1	2014-09-30	14 mi
Registration #2	2018-05-12	4.055 mi
Registration #3	2018-05-15	4.055 mi
Registration #4	2019-05-10	8.544 mi
Registration #5	2019-05-10	8.544 mi
Registration #6	2020-05-06	15.373 mi
Registration #7		11.777 mi
Registration #7 Registration #8		00.000 est
-		01.000 est 01.000 est 01.000 est
Registration #8		00.000 est 0.000 est 00.000 est 00.000 est
Registration #8 Registration #9		01.000 est 0.000 est 01.000 est 01.000 est 01.000 est





### Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	75%
Children	80%
Pedestrian	60%
Safety systems	38%
Overall rating	65%
Video	see crash video



Dimensions & weight	
Width	2011 mm
Height	1858 mm
Length	4560 mm
Wheel base	2725 mm
Kerb weight	1571 kg
Max. allowed weight	2220 kg
Additional information	
Fuel delivery	Not Applicable
Number of seats	2
Number of axles	2
Engine number Carcheck.co.uk	054101E page 12/12